

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-0-25-03029
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1482
7. Lease Name or Unit Agreement Name	
STATE BJ	
8. Well No.	1
9. Pool name or Wildcat	VACUUM GB/SA

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator ME-TEX OIL & GAS, INC.	
3. Address of Operator P.O. BOX 2070 HOBBS, NM 88240	
4. Well Location Unit Letter M : 990 Feet From The SOUTH Line and 330 Feet From The WEST Line Section 35 Township 17-S Range 35-E NMMP LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. PLUG & ABANDON SAN ANDRES (CIBP @ 4,850') 35' of Cum
2. PLUG & ABANDON QUEEN (CIBP @ 4,030')  
VERBAL APPROVAL
3. AFTER PLUGBACK, INITIATE YATES COMPLETION 3,050' - 3,450'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE BURTON VETETO TITLE PRESIDENT DATE 9/3/96  
TYPE OR PRINT NAME BURTON VETETO TELEPHONE NO. 505-397-7750

(This space for State Use)

APPROVED BY ORIGINAL SIGNATURE BY JERRY CHATON TITLE DISTRICT I SUPERVISOR DATE SEP 27 1996

CONDITIONS OF APPROVAL, IF ANY: