DISTRIBUTION	Form C-103
1 ::	Supersedes Old C-102 and C-103
	CONSERVATION COMMISSION Effective 1-1-65
1 LE	
U.S.G.S.	5a. Indicate Type of Lease
LAND OFFICE	State X Fee
OPERATOR	5. State Oil & Gas Lease No.
	E-05143-002
SUNDRY MOTICES AND DEPORT	
SUNDRY NOTICES AND REPORT (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR USE "APPLICATION FOR PERMIT -" (FORM C-101) F	OUN WELLS PLUG BACK TO A DIFFERENT RESERVOIR.
1.	
OIL V GAS	7. Unit Agreement Name
well OTHER- 2. Name of Operator	State G-36
	8. Farm or Lease Name
V. H. Westbrook	State G-36
3. Address of Operator	9. Well No.
P. O. Box 2264, Hobbs, New Mexico 88240	3, 1131 1131
4. Location of Well	
T 660	10. Field and Pool, or Wildcat
UNIT LETTER L 660 FEET FROM THE WE	St Line and 1980 FEET FROM Vacuum-San Andres
THE South LINE, SECTION 36 TOWNSHIP 1	7S 35E (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
TOWNSHIP	HANGENMPM.
15. Elevation (Show wi	bether DF, RT, GR, etc.)
16.	Lea \\\\\\\
NOTICE OF INTENTION TO:	ate Nature of Notice, Report or Other Data
	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	
TEGG AND ABANDON	REMEDIAL WORK X
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN
PULL OR ALTER CASING CHANGE PLANS	CASING TEST AND CEMENT JOB
	OTHER
OTHER	
	. L
17. Describe Proposed or Completed Operations (Clearly state all pertines work) SEE RULE 1703.	nt details, and give pertinent dates, including estimated date of starting any pro
 Describe Proposed or Completed Operations (Clearly state all pertiner work) SEE RULE 1103. 	nt details, and give pertinent dates, including estimated date of starting any pro
17. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1903. 12-18-74 Pulled rods & tubing. Ran cemen	
12-18-74 Pulled rods & tubing. Ran cemen	t retainer.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs
12-18-74 Pulled rods & tubing. Ran cemen	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cen	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cement	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cen	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cer 12-22-74 Logged & re-perforated from 4804 12-23-74 Fract w/30,000 gals. brine & 30,6	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cen 12-22-74 Logged & re-perforated from 4804	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cer 12-22-74 Logged & re-perforated from 4804 12-23-74 Fract w/30,000 gals. brine & 30,6	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cen 12-22-74 Logged & re-perforated from 4804 12-23-74 Fract w/30,000 gals. brine & 30,000 12-26-74 Swabbed well down.	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cer 12-22-74 Logged & re-perforated from 4804 12-23-74 Fract w/30,000 gals. brine & 30,6	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cen 12-22-74 Logged & re-perforated from 4804 12-23-74 Fract w/30,000 gals. brine & 30,000 12-26-74 Swabbed well down.	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cen 12-22-74 Logged & re-perforated from 4804 12-23-74 Fract w/30,000 gals. brine & 30,000 12-26-74 Swabbed well down.	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cen 12-22-74 Logged & re-perforated from 4804 12-23-74 Fract w/30,000 gals. brine & 30,000 12-26-74 Swabbed well down.	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cen 12-22-74 Logged & re-perforated from 4804 12-23-74 Fract w/30,000 gals. brine & 30,6 12-26-74 Swabbed well down.	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cen 12-22-74 Logged & re-perforated from 4804 12-23-74 Fract w/30,000 gals. brine & 30,000 12-26-74 Swabbed well down.	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cen 12-22-74 Logged & re-perforated from 4804 12-23-74 Fract w/30,000 gals. brine & 30,000 12-26-74 Swabbed well down.	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886.
12-18-74 Pulled rods & tubing. Ran cemen 12-20-74 Squeezed perforations from 4804 Drilled out cement retainer & cen 12-22-74 Logged & re-perforated from 4804 12-23-74 Fract w/30,000 gals. brine & 30,000 12-26-74 Swabbed well down.	t retainer. to 5220 with 350 sks. cement. S. I. well 48 hrs ment from 4720 to 4886. to 4886. 000 lbs. sand. S. I. well.

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

DATE 1-22-75

TITLE Operator

DATE 1-22-75