

NUMBER		COPIES RECEIVED	
DISTRIBUTION			
SANTA FE			
FILE			
U.S.G.S.			
LAND OFFICE			
TRANSPORTER	OIL		
	GAS		
PRODUCTION OFFICE			
OPERATOR			

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the Bureau on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE	X	NOTICE OF INTENTION TO SHOOT (NITRO)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER) SANDFRAC	X	NOTICE OF INTENTION (OTHER) DRILL OUT BP	X

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Roswell, New Mexico
(Place)

December 21, 1961
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Shell Oil Company Kimberlin Well No. 1 in 0
(Company or Operator) Lease
SW 1/4 SE 1/4 of Sec. 22, T. 19S, R. 35E, NMPM., Pearl-Queen Pool
(40-acre Subdivision)
Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK

(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

PROPOSED OPERATION

1. Pull rods, tubing and pump.
2. Run tubing w/bit and drill out cement and CIBP.
3. Circulate hole clean.
4. Set CIBP on WL at 5200' and cap w/cement.
5. Perforate at 4839', 4845', 4849', 4947', 4955', 4965', 5005', 5040', 5045', 5070' w/1 JS (10 3/8" holes).
6. Run 3" frac tubing w/packer to 5090', spot 260 gallons acid, set packer at 4825'.
7. Treat via 3" tubing w/25,000 gallons lease crude + 1 1/2# sand per gallon & FIA.
8. Pull frac tubing and run production string.
9. Recover load and place on production.

Approved....., 19.....
Except as follows:

Approved
OIL CONSERVATION COMMISSION

By.....

Title.....

Shell Oil Company

Company or Operator

By..... R. A. Lowery

Original Signed By

R. A. LOWERY

Position..... District Exploitation Engineer

Send Communications regarding well to:

Name..... Shell Oil Company

Address..... Box 1858, Roswell, New Mexico