

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Northeast Pearl Queen Unit
8. Well No. 12
9. Pool name or Wildcat Pearl (Queen)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3750 DF

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Water Injection Well
2. Name of Operator Tamarack Petroleum Co., Inc.
3. Address of Operator 500 W. Texas, Suite 1485, Midland, TX 79701
4. Well Location Unit Letter E : 1980 Feet From The north Line and 660 Feet From The west Line Section 24 Township 19S Range 35E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Ran in 4 1/2" casing open ended with 2 3/8" tubing to 4882' on 12/4/85.
2. Rigged up the Western Company and pumped 20 sks cement plug. Tagged plug at 4593'.
3. Displaced hole with 9.5 ppg mud.
4. Pumped 20 sks cement plug at 3172'. Top of plug at 2883'.
5. Pumped 20 sks cement plug at 1818'. Top of plug at 1529'.
6. Pumped 20 sks cement plug at 220'. Top of plug at surface.
7. Set dry hole marker.
8. Clean location.

Plugging operations began 12/4/85 per verbal approval by Eddie Seay.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randy A. McClay TITLE Engineering Manager DATE 11/16/89  
TYPE OR PRINT NAME Randy A. McClay TELEPHONE NO. 915-683-5474

(This space for State Use)

**OIL & GAS INSPECTOR**

**NOV 29 1989**

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: