NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

THE BS WITHE COO Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the average specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See addi-

		Indicate Nature of Notice b	y Checking B	elow	
NOTICE OF INTENTION TO CHANGE PLANS		Notice of Intention to Temporarily Abandon Wel	L	Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well		Notice of Intention to Plug Back	X	NOTICE OF INTENTION TO SET LINER	+
Notice of Intention to Squeeze		Notice of Intention to Acidize		NOTICE OF INTENTION	
Notice of Intention to Gun Perforate	x	Notice of Intention (Other)	x	TO SHOOT (Nitro) NOTICE OF INTENTION (OTHER)	
OIL CONSERVATION COMMANTA FE, NEW MEXICO	AISSION	Midlan (Place)	d, Texas	July 5.	1961
Following is a Notice of Int	ention to do	certain work as described below	at the	Cabot Corporation	
(0	一种。			_	
SW 4 of S	cc27	Lea	Se		M (Unit)
(40-acre Subdivision)			E,NMPM.,	Pearl-Queen	P
	FULI (FOLLOW	L DETAILS OF PROPOSEI INSTRUCTIONS IN THE RU	D PLAN OF JLES AND R	WORK EGULATIONS)	
1. Set Brid	ge Plug	at 4800'.	JLES AND R	EGULATIONS)	
 Set Bridge Perforate 	ge Plug B Casin	g at 4800.	4729'-4	EGULATIONS)	
 Set Bridge Perforate 	ge Plug B Casin	at 4800'.	4729'-4	EGULATIONS)	
 Set Bridge Perforate 	ge Plug B Casin	g at 4800.	4729'-4	EGULATIONS)	
 Set Bridge Perforate 	ge Plug B Casin	g at 4800.	4729'-4	EGULATIONS)	
 Set Bridge Perforate 	ge Plug B Casin	g at 4800.	4729'-4	EGULATIONS)	
 Set Bridge Perforate 	ge Plug B Casin	g at 4800.	4729'-4	EGULATIONS)	
1. Set Bride 2. Perforate 3. Frac with	ge Plug B Casin	g at 4800°. Ig in the interval O gal. lease oil	4729'-4	EGULATIONS) 1744'. 100# sand. bot Corporation	
1. Set Bride 2. Perforate 3. Frac with	ge Plug Casin	g at 4800°. Ig in the interval O gal. lease oil	4729'-4	EGULATIONS) 1744 . 200# sand.	
1. Set Bridge 2. Perforate 3. Frac with	ge Plug Casin	g at 4800'. Ig in the interval O gal. lease oil By	4729'-4 and 40,0	EGULATIONS) 1744'. 100# sand. bot Corporation	

Addres Dist Prod Supt