

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-70

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
B-1553	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Texaco Producing Inc.		
3. Address of Operator		9. Well No.
P. O. Box 728, Hobbs, New Mexico 88240		31
4. Location of well		10. Field and Pool, or Wildcat
UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM		Lovington San Andres
THE <u>West</u> LINE, SECTION <u>1</u> TOWNSHIP <u>17S</u> RANGE <u>36E</u> N.M.P.M.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3845' DF		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. Install BOP. Strip out Rds, pmp & tbq.
2. TIH w/4 3/4" bit and csg scraper to 4530'. TIH w/RBP & pkr. BP @ 4500'.
3. Test csg from 4500'-surface to 500#, Ok. TIH w/bit. C/O from 4922'-4960'. Drilled new 4 3/4" hole. from 4960'-5125'.
4. Ran GR/CNL/CAL/CCL from 5125'-2500'. TIH w/5 1/2" packer.
5. Acidize 4 3/4" OH from 4541'-5125' w/10,000 gals. gel 15% NEFE in 3 stages w/1000# rocksalt blocks between stages. Flushed w/50 bbls. brine. Backflow 100 bbls. to pit.
6. TOH w/ packer. Run production equipment.
7. Place on produciton.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

397-3571

SIGNED James A. Head TITLE Hobbs Area Superintendent DATE April 14, 1987

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE APR 17 1987

CONDITIONS OF APPROVAL, IF ANY: