

District I
1625 N. French Dr., Hobbs, NM 87240
District II
311 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-03858
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other WIW <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Saga Petroleum LLC		6. State Oil & Gas Lease No. B-1553
3. Address of Operator 415 W. Wall, Suite 1900 Midland, TX 79701		7. Lease Name or Unit Agreement Name State E Tract 18
4. Well Location Unit Letter G : 1650 feet from the N line and 1650 feet from the E line Section 2 Township 17S Range 36E NMPM County Lea		8. Well No. 22
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3852' Gr		9. Pool name or Wildcat Abo SWD

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER: MIT - TA <input type="checkbox"/>	
---	--	---	--

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

7-16-02 RIH w/gauge ring to 6210', no tight spots. RIH w/CIBP & set @ 6200'

7-17-02 Pressure up to 560 psi, held 520 psi for 30+ mins
Chart attached - good test - Well TA'd

Saga wants to hold wellbore for possible Queen recompletion

Approval of Temporary
Abandonment Expires

7/23/07

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 07/19/2002

Type or print name Bonnie Husband Telephone No. (915)684-4293
(This space for State use)

APPROVED BY CARY W. WINK DATE JUL 23 2002
Conditions of approval, if any: OC FIELD REPRESENTATIVE II/STAFF MANAGER

