

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-100
Revised 10-1-78

FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-3009

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☐ GAS WELL ☐ OTHER- Water Injection	7. Unit Agreement Name
Name of Operator	8. Farm or Lease Name
Texaco Producing Inc.	Lovington Paddock Unit
Address of Operator	9. Well No.
P.O. Box 728, Hobbs, NM, 88240	62
Location of well	10. Field and Pool, or WHdcat
UNIT LETTER I 1980 FEET FROM THE South LINE AND 560 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 17S RANGE 36E NMPM.	Lovington Paddock
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3843' KB	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
NULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		OTHER Temporarily abandoned	☒

1. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1603.

04-21-86 MIRU. Install BOP. Pull tubing and packer. Set 5 1/2" Howco EZ Drill BP on wireline at 6043'. (Top perforation @ 6169'). Run tubing open ended, tag BP.

04-22-86 Circulated treated water. Pull and lay down tubing. Shut well in. RD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Dist. Adm. Supvr. DATE 05-12-86

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

MAY 20 1986