Submit 3 Copies to Appropriate District Office	State of New Mi Energy, Minerals and Natural R		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION		WELL API NO.
P.O. Box 2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 P.O. Box 2088 Santa Fe, New Mexico 87504-2088		30-025-03881 5. Indicate Type of Lease	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE     FEE       6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			B-3009 7. Lease Name or Unit Agreement Name
1. Type of Well: OIL WELL XX WELL	CTTHEFR		West Lovington Unit
2. Name of Operator GREENHILL PETROLEUM (			8. Well No. 33
<ol> <li>Address of Operator 11490 Westheimer, Sui</li> </ol>	Ite 200, Houston, Texas	77077	9. Pool name or Wildcat (April) Lovington San Andres West
4. Well Location Unit Letter <u>P</u> : 660	) Feet From The South	Lipe and 66	ç •
Section 5	170	ange 36E	NMPM Lea County
	Appropriate Box to Indicate I		-
		SUB	SEQUENT REPORT OF:
		REMEDIAL WORK	
	CHANGE PLANS	COMMENCE DRILLING	
PULL OR ALTER CASING	[]	CASING TEST AND CEMENT JOB Deepen, stimulate and convert to	
12. Describe Proposed or Completed Opera	tions (Clearly state all pertinent details as	injectio	n WPX-609
work) SEE RULE 1103.			
			g of 2 3/8" tubing. Pressure up
casing to 485#. Ran	chart for 30 minutes.	Ending pressur	e was 510#. Increase due to
thermal expansion.			
r			
-	CO2 and 3000 gallons	of 20% NEFE HC1	Acid.
Treat with 15 tons of		of 20% NEFE HC1	Acid.
-		of 20% NEFE HC1	Acid.
Treat with 15 tons of $3\frac{1}{2}$ diag show the $3\frac{1}{2}$	e and complete to the best of my knowledge and		
Treat with 15 tons of "" "" g that the information above is true SKONATURE Archael form	e and complete to the best of my knowledge and		Permian Basin Date 2-4-92
Treat with 15 tons of """"""""""""""""""""""""""""""""""""	e and complete to the best of my knowledge and		
Treat with 15 tons of The stage show all the I hereby certify that the information above is true SKONATURE	e and complete to the best of my knowledge and		Permian Basin Date 2-4-92
Treat with 15 tons of """ """""""""""""""""""""""""""""""""	e and complete to the best of my knowledge and Newport	ы.а. ur Land Manager-I	2ermian_Basin_ date2-4-92 TELEPHONE NO.713_589-84