

STATE OF NEW MEXICO
OIL AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

TO: BY: (NAME AND ADDRESS)	
DISTRIBUTION	
SANTA FE	
FILE	
S. C. S.	
AND OFFICE	
PERMIT	

34. Indicate Type of Lease
State ☒ Fee ☐
3. State Oil & Gas Lease No.
B-3009

SUNDARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG SALS TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - FORM C-101, FOR SUCH PROPOSALS.)

1. ☒ GAS WELL ☐ OTHER

7. Unit Agreement Name
West Lovington Unit

2. Operator
TEXACO PRODUCING INC.

8. Form or Lease Name

3. Address of Operator
P.O. BOX 728, HOBBS, N.M. 88240

9. Well No.
32

4. Location of Well
IT LETTER 0 660 FEET FROM THE South LINE AND 660 FEET FROM
West LINE, SECTION 5 TOWNSHIP 17S RANGE 36E

10. Field and Pool, or Wildcat
Lovington San Andres

Un

11. Elevation (Show whether DF, RT, GR, etc.)
12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
REARLY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. POH w/production equipment.
2. PSA 4433'. P/15 BW, 15 gal 425 Inhib. & 3 drums Techni-Hib 405 Scale Inhib.
3. PSA 4125'. P/2000 gal 15% gelled acid w/50 bbls. gelled wtr. 100# SLT and 100# acid flakes.
4. P/2000 gal 15% gelled acid overflushed w/20 BW.
5. TIH w/production equipment. Test and place on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Dist. Opr. Mgr.

10/23/85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

OCT 28 1985

RECEIVED

OCT 25 1985

O.C.D.
HOBBS OFFICE