

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.

1. Name of Operator TEXACO Inc.		5a. Indicate Type of Lease State ☒ Fee ☐	
2. Address of Operator P.O. Box 728, Hobbs, NM 88240		5. State Oil & Gas Lease No. B-4120	
3. Location of Well UNIT LETTER H YEAR FROM THE 1980 <i>North</i> South LINE AND 660 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 17-S RANGE 36-E NNIPM		7. Unit Agreement Name West Lovington Unit	
		8. Form or Lease Name West Lovington Unit	
		9. Well No. 53	
		10. Field and Pool, or Wildcat Lovington San Andres West	
11. Elevation (Show whether DF, RT, GR, etc.) 3905' (DF)		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Install BOP. Pull tubing & pkr.
2. Clean out to 5110'.
3. Set pkr @ 4300'. Acidize open hole 4717-5110' w/1800 gal. 15% NEAcid in 2 stages using 500# rock salt between stages.
4. Install injection equipment. Test & return to injection.

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Jerry Sexton* TITLE Asst. Dist. Supt. DATE 9-20-79
 ORIG. SIGNED BY Jerry Sexton
 APPROVED BY Dist. 1. Supv. TITLE _____ DATE SEP 24 1979
 CONDITIONS OF APPROVAL, IF ANY: