

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-7896	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR THE LOCATION OF WELL OR TO OPEN OR CLOSE WELL TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT TO DRILL OR TO CLOSE WELL FOR SUCH PURPOSES.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: convert producer to injector		7. Unit Agreement Name Lovington Paddock Unit
2. Name of Operator Getty Oil Company		8. Farm or Lease Name
3. Address of Operator P.O. Drawer DD, Levelland, Texas 79336		9. Well No. 1 53
4. Location of Well UNIT LETTER A 330 FEET FROM THE North LINE AND 840 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 17-S RANGE 37-E N.M.P.M.		10. Field and Pool, or Wildcat Lovington-Paddock
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: convert producer to injector <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

## Converting Procedure

1. POH w/rods and pump.
2. Installed BOP. Tagged T.D. w/tbg., POH w/tbg.
3. WIH w/R-4 injection packer on 2-3/8" plastic coated tubing.
4. Load casing with inhibited fluid.
5. Hook well to injection system and start injecting.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E.P. Morales *E.P. Morales* TITLE area engineer DATE 12-16-80

APPROVED BY Jerry Sexton TITLE  DATE

CONDITIONS OF APPROVAL Dis. L. Sexton