

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Salt Water Disposal		7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation		8. Farm or Lease Name Knowles SWD
3. Address of Operator P.O. Drawer "D", Monument, New Mexico 88265		9. Well No. 1
4. Location of Well UNIT LETTER D 660 North 660 FEET FROM THE LINE AND FEET FROM West 2 17-S 38-E THE LINE, SECTION TOWNSHIP RANGE NMPM.		10. Field and Pool, or Wildcat Knowles
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran gauge ring to 50'. Ran bit and casing scraper to 2450'. Set cast iron bridge plug at 2450' with 35' cement cap. Loaded casing with brine gel. Shot casing at 1300'. Attempted to pull with no results. Squeezed 75 sx. cement down 5-1/2" casing. Max. PP 400#. Tagged top of cement at 1000'. Shot 5-1/2" casing at 312'. Squeezed 85 sx. cement down 5-1/2" casing. Max. PP 500#. Top of cement at 30'. Spotted 10 sx. cement plug with dry hole marker in top of casing.  
WELL PLUGGED AND ABANDONED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>MC Black</i>	TITLE Supver., Admin. Services	DATE 11-13-75
APPROVED BY <i>John W. Ramsey</i>	TITLE	DATE
CONDITION OF APPROVAL, IF ANY:		