

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-07300</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name W. F. Cone
8. Well No. 2
9. Pool name or Wildcat Knowles, S. (Devonian)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,700'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator F&M Oil and Gas Company	3. Address of Operator P.O. Box 891, Midland, Texas 79702	4. Well Location Unit Letter <u>0</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1,980</u> Feet From The <u>East</u> Line Section <u>12</u> Township <u>17S</u> Range <u>38E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,700'			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: Confirm that work was performed to <input checked="" type="checkbox"/> T&A Cone #2		OTHER: <u>Abandon Devonian</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-8-88

Move in and rig up pulling unit. Toh and lay down rods. NU BOP. Rel. TAC and begin to TOH with Tubing. SDFN. SI.

7-9-88

Finish TOH with production Tubing. Rig up wireline unit. Made gamma ray and junk basket run to 12,144'. Ran CIBP and set at 12,103'. Cap with 35' cement slurry. Rig down WLU. TIH with prod. tubing to 11,982'. Displace hole with packer fluid and corrosion inhibitor. TOH with prod. Tubing laying same down. ND BOP. Nipple up flange with Valve. Rig down pulling unit and move off location. Well #2 is TA'D* (* End of report on 7-11-88 This is a 72 HOUR SUMMARY)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randall Foster TITLE Vice President DATE 1-20-93

TYPE OR PRINT NAME Randall Foster TELEPHONE NO. 915 682-7714

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 25 1993

RECEIVED
JAN 22 1993
OCD HOBBS OFFICE