NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, See the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Notice by Checki	ng Below	
otice of Intention o Change Plans	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper	
OTICE OF INTENTION O PLUG WELL	Notice of Intention to Plug Back	Notice of Intention to Set Liner	
o Squeeze	Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)	
JOTICE OF INTENTION O GUN PERFORATE	Notice of Intention (Other)	Notice of Intention (Other)	
DIL CONSERVATION COMMISS ANTA FE, NEW MEXICO	ION Hidland, Texas (Place)	Sept. 1954	••••
Gentlemen:			
Following is a Notice of Intention	on to do certain work as described below at the	D. F. Willhoit	••••••
Jake L. Hanon & War	ren Peta Corpa	Well Noinin	D
1/4 of Sec.	18, T175, R39K,N	IMPM., South Knowles Devonian	1
Les.			
	County.		
	FULL DETAILS OF PROPOSED PL	AN OF WORK	
(FC	FULL DETAILS OF PROPOSED PLOLLOW INSTRUCTIONS IN THE RULES		
	OLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	
		AND REGULATIONS)	l io
	OLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	40
	OLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	40
	OLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	le.
	OLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	40
	OLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	łs.
	OLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	lio.
	OLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	li o
	OLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	les.
	OLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	lio.
	OLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	lio
	OLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	le.
Plan to acidine from	12,160° to 12,190° w/500 gal i	AND REGULATIONS)	ileo
Plen to ecidine from	12,160° to 12,190° w/500 gal i	AND REGULATIONS)	4.
Plen to acidize from	12,160' to 12,190' w/500 gal 1	AND REGULATIONS)	
Plen to ecidine from	12,160° to 12,190° w/500 gal 1	Doloflush by Western en 9/8/5	4.
Plen to acidine from SER 11 19 Approved	12,160° to 12,190° w/500 gal 1	Doloflush by Western on 9/8/5	4.
Plen to acidize from SEP 11 15 Approved	12,160° 12,190° w/500 gal 1	Doloflush by Western en 9/8/5	-
Plen to acidine from SER 11 19 Approved	12,160° 12,190° w/500 gal 1	Doloflush by Western on 9/8/5	
Plen to acidize from SEP 11 15 Approved	12,160' 12,190' w/500 gal 1 13,160' 12,190' w/500 gal 1 By	Doloflush by Western on 9/8/5	4.
Plen to acidize from SEP 11-15 Approved	12,160' 12,190' w/500 gal 1 13,160' 12,190' w/500 gal 1 By	Doloflush by Western on 9/8/5 Company of Article Corp. Send Communications regarding well to:	