

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE  
(Other instructions on  
reverse side)Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

LC 063441

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <b>WIW</b>		7. UNIT AGREEMENT NAME <b>YOUNG UNIT</b>	
2. NAME OF OPERATOR <b>NEWMONT OIL COMPANY</b>		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR <b>P. O. BOX 1305, ARTESIA, NEW MEXICO 88210</b>		9. WELL NO. <b>25</b>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  <b>990' FSL &amp; 1650' FEL Sec. 20;T-18S;R-32E</b>		10. FIELD AND POOL, OR WILDCAT <b>YOUNG QUEEN</b>	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>Sec.20-18S-32E NMPM</b>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH <b>LEA</b>	
		13. STATE <b>NEW MEXICO</b>	

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

**Convert well to WIW**

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was converted to WIW as follows:

11-30-69 Cleaned out from 4075' to 4090'

12-2-69 Logged &amp; perforated with 2 jet shots per foot 3797'-3806', 3808'-14', 3819'-28', 3832'-34', 4043'-47'

12-23-69 Fraced well with 500 gallons 15% regular acid, 36,000# 20/40 sand, and 942 bbls fresh water

12-31-69 Cleaned out

1-1-70 Cleaned out to 4087'

1-2-70 Put well on injection

Injection first five days averaged Upper Queen 122 BPD @ 750 psi,  
Penrose 175 BPD @ 0 psi.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Thomas L. L. L.*

TITLE

Division Superintendent

DATE

1-26-70

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

DATE

JAN 29 1970

\*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO