## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

MAY 1 0 1996

Submit 3 Copies Revised 1-1-89 to Appropriate District Office OIL CONSERVATION DIVISION WELL API NO. DISTRICT I 30-025-08455 P.O. Box 2088 P.O. Box 1980, Hobbs NM 88240 Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease DISTRICT II STATE X FEE 🗌 P.O. Drawer DD, Artesia, NM 88210 6. State Oil & Gas Lease No. DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" M. E. HALE (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: GAS WELL WELL X 8. Well No. 2. Name of Operator Phillips Petroleum Company 9. Pool name or Wildcat 3. Address of Operator VACUUM (GB/SA) 4001 Penbrook Street, Odessa, TX 79762 WEST 1980 4. Well Location Line Feet From The SOUTH Line and 660 Feet From The Unit Letter County NMPM 17-S Rango Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Section 4029 RKB Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. CHANGE PLANS TEMPORARILY ABANDON CASING TEST AND CEMENT JOB PULL OR ALTER CASING OTHER: RUN PUMP-IN TRACER OTHER: . 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 02/19/96 MIRU DIAMOND RENTAL DDU, CCOHW/ RODS, PUMP, NU BOP ND WELL HEAD RELEASE TAC, DROP DOWN AND TAG CIBP AT 4570', PU TO END OF TBG 02/20/96 RU CARDÍNAL, RUN TEMP SURVEY, RELAND TBG, SET TAC, RUN PUMP, RIG RIG DOWN DDU, **9** 4307', SISD. RIG DOWN DDU, WELL PUMPING TO BATT. 02/23/96 MIRU CARDINAL SURVEY, LOG AS PER PROCEDURE, RDMO CARDINAL, START FLOWING, TEMP DROP FROM REPORT. 02/26/96 MIRU DDU CCOH W/RODS-PUMP, NU BOP ENVIRO, PAN ON WELL, RELEASE TAC, COOH W/PROD TBG, GIH W/PKR ON PROD TBG, LEFT PKR SWINGING, SDON 02/27/96 SET PKR @ 4401', ND BÓP, NU WELL HEAD, RÚ JSI WIRE LINE GIH W/TANDEM STARBURST ULTR ELECTRONIC GAUGES, SET IN MUD ANCHOR AT 4475', RUN PUMP, ROD STRING, LOAD TBG, CHECK PUMP ACTION, PUT WELL ON TEST, LEFT DDU OVER WELL ( OVER ) I hereby certify that the information above is true and complete to the best of my knowledge and belief. THILE Senior Regulation Analyst DATE 4/05/96 SIGNATURE \_\_\_\_ TELEPHONE NO. (915) 368-1488 TYPE OR PRINTNAME | arry M. Sanders

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

(This space for State Use)

1938 34 CN

02/29/96	16 HR TEST: .4 BBL OIL, 82 BBL WTR, 0.0 MCF GAS, 50 PSI ON TBG 0 PSI
	ON CASING, 20 BBL WTR (TO KILL GAS PRESS) T/PECOVER
03/01/96	24 HR TEST: 0 BBL OIL 40 BBL WTR 0 GAS 45 PSI ON TRG/FI OWI DIE 0
	PSI ON CSG, WELL GAS LOCKED, SI WELL 7 DAY PRESS BUILDUP
	IESI.
03/04/96	SI, PRESS BUILD UP TEST: 3/1/96 50 PSI TBG 0 PSI CSG, 3/2/96 50 PSI
	TBG, 0 PSI CSG, 3/3/96 35 PSI TBG, 0 PSI CSG, 3/4/96 35 PSI TBG, 0 PSI
	CSG.
03/05/96	SI F/PRESS BUILD UP TEST: 3/5/96 35 PSI TBG 0 PSI CSG.
03/06/96	SI, TBG PRESS 30 CSG PRESS 0 PSI.
03/07/96	MIRU DIAMOND RENTAL #751. COOH W/RODS & PMP PILISI
	WIRELINE, RUN IN FISH PRESSURE GAUGES, COOH, RD JSI, NU BOP,
	ND WELLHEAD, SD.
03/08/96	RELEASE PKR, COOH W/TBG, RUN IN W/PROD TBG, ND BOP, NU
	WELLHEAD, RUN ROD STRING, PMP, LOAD TBG, CK PMP ACTION, RD
	DDU. COMPLETE DROP FROM REPORT.