

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-20339-08535
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	NM-631
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	88
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4002' DF	

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter M : 660 Feet From The SOUTH Line and 660 Feet From The WEST Line
Section 31 Township 17S Range 35E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4002' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-20-99: MIRU. NDWH. NUBOP.
9-21-99: TIH W/NEW BIT, DC'S. & WS. STOP BIT @ 4190'.
9-22-99: TIH W/BIT & TOOLS. TAG FILL IN O.H. @ 4685'. C/O FILL TO 4710' (PBD). DRILL NEW HLE TO 4780'. PULL BIT TO 4250'.
9-23-99: LOWR BIT TO 4710'. BREAK CIRC. LOWER TOOLS TO 4780'. DIRLL NEW HLE 4780-4800'. TIH W/UNDR REAMER, JARS, DC'S & TBG. STOP REAMER @ 4250'.
9-24-99: TIH TO 4290'. BREAK CIRC. UNDER REAM O.H. TO 6 1/4" 4290-4670'. HARD DRLG @ 4670-4710'. STASRT REAMING NEW HLE 4710-15'. PULL REAMER TO 4297'.
9-25-99: TIH W/REAMER TO 4715'. REAM NEW HLE 4715-4742'. TIH W/NEW REAMER, JARS, DC'S & TBG TO 4250'.
9-27-99: UNDER RAM NEW HLE 4742-4800' TO 6 1/4" OPEN HLE. PULL REAMER TO 4297'.
9-28-99: TAG UP @ 4800'. RAN GR/CNL/DENSITY LOG W/CALIPER 4800-4200. TIH W/PKR, SN, TBG. PSA 4206'. LOAD PSI CSG TO 500-OK.
9-29-99: PSI CSG TO 500-OK. ACIDIZE OPEN HOLE 4280-4800' W/5000 GALS 20% HCL NEFE & 2000# RK SLT. RU SWAB. END FL @ 1100'.
9-30-99: FL @ 1100'. END FL @ 2300'. SCALE SQZ W/275 GALS TH-756.
10-01-99: INSTL CHANGE OVER FLANGE. NUBOP. UNSET PKR. TIH W/BIT ON TBG. TAG FILL @ 4795'.
10-02-99: TIH W/MOTOR, SEPR, PUMP, TBG. NDBOP. NU NEW QCI WH & GATE VALVE. WELL PUMPING @ 12:47 PM. RIG DOWN.
10-05-99: ON 24 HR OPT. PUMPING 55 BO, 1650 BW, & 15 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 10/12/1999

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

ORIGINAL SIGNED BY

(This space for State Use)

APPROVED BY GARY WINK TITLE FIELD REP II DATE OCT 18 1999

CONDITIONS OF APPROVAL, IF ANY:

