

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-08539 08538
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1400-3
7. Lease Name or Unit Agreement Name East Vacuum Gb/SA Unit Tract 3315
8. Well No. 002
9. Pool name or Wildcat Vacuum Gb/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762	
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 33 Township 17-S Range 35-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3941' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Cleaned out and acidized ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-24-93 - MIRU DDU. COOH w/sub equip. Trip sand pump. Tag @4635'. Catch sample of calcium sulfate scale. GIH w/bit and scraper to 4250'.
7-27-93 - COOH w/tbg. & csg. scraper. Set pkr. @4187'. Pump 20 bbls. fresh water w/10 gals. 425. Pump 1/2 of 3 drum 405 and 165 gals fresh water mix out of tbg. Test csg. to 500#. O.K. Wait 3 hrs. and pump rest of mix.
7-28-93 - RU swab. Pull & reset pkr. @3751'. Pump 5500 gals 15% NeFe HCl acid.
7-29-93 - Swab.
7-30-93 - MIRU and pump 10 gals 430 in 20 bbls. fresh water, 10 bbls fresh water, 5 drums 757 in 50 bbls. fresh water, 500 bbls. fresh water.
7-31-93 - COOH w/tbg. & pkr. PU GIH w/sub equip. and tbg. NDBOP. Flange up wellhead. Start pumping.
8-03-93 - Test 24 hrs.: 178 BOPD; 668 BWPD; 312.0 Mcf; 1756.163 GOR.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supv., Regulatory Affairs DATE 08-04-93
TYPE OR PRINT NAME L. M. Sanders (915) 368-1488
TELEPHONE NO. 368-1488

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE AUG 09 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

10 9 1993

W. HOBBS
OFFICE