| SANTA FE FILE | ISTRIBUTION | | | | | | | | | |
|---|---------------------------------------|------------------------------|--------------------|--|--|---|--|---|-----------------------------------|--|
| FILE | | | | | | | | | | |
| U.S.G.S. | | | | | | | | COMMISSI | - • • | FORM C-103 |
| LAND OFFICE | 011. | | | MISCEL | | | - | Swavel Las | | (Rev 3-55) |
| PRORATION OFF | GAS | | | MIJCEL | LAILU | UJ KEP | OKISU | 974° . W JEJE (13 | FILE | 900 |
| Name of Comp | | | (Submit | to appropr | riate Disti | rict Office | as per Ca | mmission Ru | le 1106) |) |
| | Phil: | lips Petr | oleum Ca | mpany | Add | ress Box | 2105 - 1 | Hobbs, Nev | | |
| Lease | Santa Fe | | W | /ell No. 69 | Unit Lette | er Section 26 | Township | 9 | Range | 35- I |
| Date Work Per May 22,23 | ,24, 1962 | Pool | Undes | ignated | | | County | Lea | | |
| | | | THIS IS A | AREPORT | OF: (Chec | k approprie | zte block) | | | |
| 🔲 Beginnin | g Drilling Ope | rations | 🗶 Casi | ing Test and | l Cement J | ob | Other (| (Explain): | | •••••••••••••••••••••••••••••••••••••• |
| Plugging | : | | Rem | edial Work | | | | | | |
| Detailed accou | unt of work do | ne, nature and | d quantity of | materials u | ised, and r | esults obta | ined. | | | |
| | | | | | | | | | | |
| Witnessed by C. L. Sumerwell Po | | | | | | | | | | |
| | C. L. | Sumerwell | | Position Lease | Forma | a | Company Phi | llips Pet: | roleum | |
| | C. L. | | L IN BELO | Lease | MEDIAL | A WORK RE | Phi | llips Pet: | roleum | . Co. |
| | · · · · · · · · · · · · · · · · · · · | FIL | | Lease DW FOR RE ORIGIN | | A WORK RE | Phi PORTS 0 | NLY | roleum | Go. |
| D F Elev. | · · · · · · · · · · · · · · · · · · · | | | Lease | MEDIAL | A WORK RE | Phi | NLY | | a Go. |
| | î | FIL | L IN BELO | Lease DW FOR RE ORIGIN | MEDIAL | A WORK RE | Phi PORTS 0. Producing | NLY 3 Interval | | pletion Date |
| D F Elev. | er]] | FIL T D | L IN BELO | Lease DW FOR RE ORIGIN | MEDIAL | NORK RE | Phi PORTS 0. Producing | NLY 3 Interval | Com | pletion Date |
| D F Elev. Tubing Diamete | er rval(s) | FIL T D | L IN BELO | Lease DW FOR RE ORIGIN | Oil St | WORK RE DATA | Phi PORTS 0 | NLY 3 Interval | Com | pletion Date |
| D F Elev. Tubing Diamete Perforated Inte | er rval(s) | FIL T D | L IN BELO | Lease DW FOR RE ORIGIN PBTD | Oil Str | WORK RE DATA ring Diamet | Phi PORTS 0 | NLY 3 Interval | Com | pletion Date |
| D F Elev. Tubing Diamete Perforated Inte | er rval(s) rval | FIL FD Tubing | L IN BELO | Lease DW FOR RE ORIGIN | Oil Str | WORK RE DATA ring Diamet | Phi PORTS 0 | NLY 3 Interval | Com | pletion Date |
| D F Elev. Tubing Diameta Perforated Inte Open Hole Inte Test | er rval(s) | FIL FD Tubing Oil F | L IN BELO | Lease DW FOR RE ORIGIN PBTD RESULTS Gas Pro | Oil Str | MORK RE DATA ring Diamet cing Forma RKOVER Water Pi | Phi PORTS 0 | NLY 3 Interval | Com ng Depth | pletion Date |
| D F Elev. Tubing Diameto Perforated Inte Open Hole Inte | er rval(s) rval Date of | FIL FD Tubing Oil F | L IN BELO Depth | Lease DW FOR RE ORIGIN PBTD RESULTS Gas Pro | Oil Str Production | MORK RE DATA ring Diamet cing Forma RKOVER Water Pi | Phi PORTS 0. Producing ter tion(s) | NLY 3 Interval Oil Strin GOR | Com ng Depth | Gas Well Potential |
| D F Elev. Tubing Diameto Perforated Inte Open Hole Inte Test Before | er rval(s) rval Date of | FIL FD Tubing Oil F | L IN BELO Depth | Lease DW FOR RE ORIGIN PBTD RESULTS Gas Pro | Oil Str Production | MORK RE DATA ring Diamet cing Forma RKOVER Water Pi | Phi PORTS 0. Producing ter tion(s) | NLY 3 Interval Oil Strin GOR | Com ng Depth | Gas Well Potential |
| D F Elev. Tubing Diameta Perforated Inte Open Hole Inte Test Before Workover After | rval(s) rval Date of Test | FIL FD Tubing Oil F | L IN BELO | Lease DW FOR RE ORIGIN PBTD RESULTS Gas Pro | Oil States of WOR Oduction FPD | A WORK RE DATA ring Diamet cing Format RKOVER Water Pi B B | Phi PORTS 0 Producing ter tion(s) | NLY 3 Interval Oil Strin GOR Cubic feet/2 oformation give | Com ng Depth Bbl | Gas Well Potential |
| D F Elev. Tubing Diameta Perforated Inte Open Hole Inte Test Before Workover After | rval(s) rval Date of Test | FIL T D Tubing | L IN BELO | Lease DW FOR RE ORIGIN PBTD RESULTS Gas Pro | Oil States of WOR Oduction FPD | A WORK RE DATA ring Diamen cing Format RKOVER Water Ph B Water Ph B | Phi PORTS 0 Producing ter tion(s) roduction PD | NLY 3 Interval Oil Strin GOR Cubic feet/2 oformation give | Com ng Depth Bbl | Gas Well Potential MCFPD |
| D F Elev. Tubing Diameta Perforated Inte Open Hole Inte Test Before Workover After Workover | rval(s) rval Date of Test | FIL T D Tubing | L IN BELO | Lease DW FOR RE ORIGIN PBTD RESULTS Gas Pro | Oil Str Oil Str Production FPD | A WORK RE DATA ring Diamet cing Forma KOVER Water P B B water P B B cing teby certify the best of n | Phi PORTS 0 Producing ter tion(s) roduction PD | NLY 3 Interval Oil Strin GOR Cubic feet/ Information give ge. | Com ng Depth Bbl n above | Gas Well Potential MCFPD |
| D F Elev. Tubing Diameto Perforated Inte Open Hole Inte Test Before Workover After Workover | rval(s) rval Date of Test | FIL T D Tubing | L IN BELO | Lease DW FOR RE ORIGIN PBTD RESULTS Gas Pro | Oil Str Oil Str Product S OF WOR oduction F P D | A WORK RE DATA ring Diamed cing Forma RKOVER Water Ph B B Water Ph B B Construction B Construction B Construction Construc | Phi PORTS 0 Producing ter tion(s) roduction PD that the in ny knowledg | NLY 3 Interval Oil Strin GOR Cubic feet/2 oformation give | Com ng Depth Bbl n above | Gas Well Potential MCFPD |