

DISTRICT I

P.O. Box 1930, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 08545
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease	B-1501
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	33
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3989' DF

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
P.O. BOX 730, HOBBS, NM 88240

4. Well Location
Unit Letter O : 660 Feet From The SOUTH Line and 1980 Feet From The EAST Line
Section 30 Township 17S Range 35E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATIONS ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CASING INTEGRITY TEST FOR TA STATUS ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/4-94 - 1/5/94

1. NOTIFIED NMOC. TOH W/ PRODUCTION EQUIPMENT.
2. SET CIBP @ 4065' & CAPPED W/ 35' CMT, PBTD @ 4030'.
3. CIRCD HOLE W/ INHIBITED FLUID & TSTD AS PER NMOC GUIDELINES TO 520# FOR 30 MIN, HELD OK.
4. TOH W/ TBG. REQUEST TEMPORARILY ABANDON WELL STATUS THROUGH 1/1/99.

(ORIGINAL CHART ATTACHED, COPY OF CHART ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE Engr Asst DATE 1/19/94

TYPE OR PRINT NAME Monte C. Duncan Telephone No. 397-0418

(This space for State Use)


APPROVED BY JERRY SEXTON
CONDITIONS OF APPROVAL, IF ANY: DISTRICT I SUPERVISOR

DATE JAN 24 1994

This Approval of Temporary
Abandonment Expires 1-1-99


SHD

12



OUR Tom Sebastian
PACKER TYPE CRP w/ 35' cmf
PACKER SETTING DEPTH 4030 (187m)
PERFORATIONS Open Hole 4104 to 4185

CLEP 4/35' 30" 10
1030' L.A.



Temporary Abandon

DATE JAN 4, 1994

WELL NAME Central Vacuum Unit #33

SUPERVISOR Tom Sebastain

PACKER TYPE CIBP w/ 35' cmt

PACKER SETTING DEPTH 4030 (PBM)

PERFORATIONS Open Hole 4104 to 4185

DISTRICT I
P.O. Box 1930, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 08545
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-1501
7. Lease Name or Unit Agreement Name CENTRAL VACUUM UNIT	
8. Well No.	33
9. Pool name or Wildcat	VACUUM GRAYBURG SAN ANTONIO

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator TEXACO EXPLORATION AND PRODUCTION INC.
3. Address of Operator P.O. BOX 730 HOBBS, NM 88240	4. Well Location Unit Letter <u>0</u> : <u>6660</u> Feet From The <u>S</u> Line and <u>1980</u> Feet From The <u>E</u> Line Section <u>30</u> Township <u>17S</u> Range <u>35E</u> NMPM <u>LEA</u> County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3989 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) NOTIFY OGD.
- 2) T.O.H. WITH ALL PRODUCTION EQUIPMENT.
- 3) BY WIRELINE SET CIBP ABOVE OPEN HOLE AT APPROX. 4029'.
- 4) BY WIRELINE CAP WITH 35' CMT.
- 5) CIRCULATE HOLE WITH INHIBITED FLUID.
- 6) TEST CSG AND PLUG.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE William T. Lackey TITLE PRODUCTION ENGR DATE 12-28-93
TYPE OR PRINT NAME WILLIAM T. LACKEY TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY TITLE DATE DEC 29 1993

CONDITIONS OF APPROVAL, IF ANY: