NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES OCT 2 2 07 PH '63

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS	Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	
NOTICE OF INTENTION TO PLUG WELL	Notice of Intention to Plug Back		Notice of Intention to Set Liner	
NOTICE OF INTENTION TO SQUEEZE	Notice of Intention to Acidize	x	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	Notice of Intention (Other)		Notice of Intention (Other)	
OIL CONSERVATION COMMISSI SANTA FE, NEW MEXICO	DN Hobbs, New Mexic	20	10-2-63	
Gentlemen:				
	to do certain work as described below at ew Mexico "O" NCT-1			
(Company or O NE 1/4 SW 1/4 of Sec (10-acre Bubdivision)	ew Mexico "O" NCT-1 perstor) Lesse 36 , T. 17S , R. 34E	, NMP M	Undesignated Abo North	(Unit) Pool
Lea				
	FULL DETAILS OF PROPOSED LOW INSTRUCTIONS IN THE RUI			
To inc	rease production we propose	e to do	the following work:	
1. Spot 35 barrels inhib	ited water in 3-1/2" casing	g from	11,100' to approximately 6	6650 '

- with the 1-1/2" tubing that is in hole. Pull tubing and set bridge plug at 11,100' and cap with Hydromite.
- 2. Orientate perforate 3-1/2" casing with one hole each at 6649', 6667' and 6682'.
- 3. Spot 15% LSTNE acid over perforations and break down formation with 3/500 gallon stages using one ball sealer after each of the first two stages.
- 4. Pull tubing and fracture down 3-1/2¹¹ casing with 10,000 gallons of refined oil and 10,000 pounds sand using 400 cubic feet of CO₂ per barrel of treatment and flush. (This amount of CO₂ equals the 8 ton minimum charge). Flow back load oil.
- 5. Run 2" 0.D. Buttress tubing with special clearance couplings, swab to clean up, and place on production. (2" 0.D. Buttress tubing is preferred over 1-1/2" to provide adequate artificial lift installation).

Approved	्र्ा		TEXACO Inc.
Except as follows:	· · · · · · · · · · · · · · · · · · ·		By
Approved OIL CONSERVATI			Position Assistant District Superintendent Send Communications regarding well to:
By Zata		•	NameJ. G. Blevins, Jr.
Title		********	Address. P.O. Drawer 728, Hobbs, New Mexico