

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-20046
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE
State Oil & Gas Lease No. B-155
Lease Name or Unit Agreement Name Vacuum Giorieta West Unit
Well No. 130
Pool name or Wildcat Vacuum Giorieta
Well Location Unit Letter N 519 Feet From The South Line and 1839 Feet From The West Line Section 36 Township 17-S Range 34-E NMPM Lea County
Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: OIL WELL GAS WELL OTHER Condensate
Name of Operator Texaco E & P Inc.
Address of Operator P.O. Box 3109 Midland, Texas 79702
Well Location Unit Letter N 519 Feet From The South Line and 1839 Feet From The West Line Section 36 Township 17-S Range 34-E NMPM Lea County
Elevation (Show whether DF, RKB, RT, GR, etc.)

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK
TEMPORARILY ABANDON
PULL OR ALTER CASING
OTHER:

PLUG AND ABANDON
CHANGE PLANS

SUBSEQUENT REPORT OF:

REMEDIAL WORK
COMMENCE DRILLING OPNS.
CASING TEST AND CEMENT JOB
OTHER:

ALTERING CASING
PLUG AND ANBANDONMENT ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-14-98 Notify OCD of intent to re-plug well
5-20-98 Drill cement out of "Y" string from 34' to 576' to 1220' to 1759'
5-25-98 Perf 4 holes @ 2293', Sqz 50 sx cement WOC & tag @ 2133'
Spot 10 sx cement from 1752' to 1346'
5-26-98 Perf 4 holes @ 30' & circulate 30 sx cement to surface
5-27-98 Drill cement out 2 7/8" csg from surface to 30', csg parted, cleanout/drill to 1498'
5-28-98 Spot 60 sx cement @ 1498', WOC & tag @ 1198
5-28-98 Spot 25 sx cement @ 62' to surface
5-29-98 Cut off well head, install dry hole marker, clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

N. Wayne Brooks

TITLE Operations Supervisor

DATE 06-02-98

TYPE OR PRINT NAME N. Wayne Brooks

TELEPHONE NO. (915) 683-5321

(This space for State Use)

APPROVED BY

Johnny Robinson

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: