

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

| |
|--|
| WELL API NO. 30/025-20115 |
| Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| State Oil & Gas Lease No. 268 |
| Lease Name or Unit Agreement Name McCallister State |
| Well No. 7 |
| Pool name or Wildcat Vacuum, Blinberry |

| | |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER | |
| Name of Operator Marathon Oil Company | |
| Address of Operator P.O. Box 2409 Hobbs, New Mexico 88240 | |
| Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1780</u> Feet From The <u>West</u> Line Section <u>25</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>Lea</u> County | |
| Elevation (Show whether DF, RKB, RT, GR, etc.) GL 4005 KB 4017 | |

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

07/10/00--Notify NMOCD of intent to plug
07/11/00--Set CIBP @ 6350, circulate hole w/10# MLB
07/12/00--Spot 25 sx cement 6350-6198
07/13/00--Stretch csg, 3500 free, set back on slips
07/14/00--Perf @ 5056, unable to pump into perfs, notify OCD, spot 40 sx cement 5118-4874
07/17/00--Tag @ 4901, cut csg @ 3500, started to flow out 10 3/4 after cutting, pump 120 bbls 10# brine
07/18/00--Marathon and OCD agreed to leave 7" in the well, spot 40 sx cement, 3553-3315
07/19/00--Tag @ 3367, perf @ 2000, set packer @ 1680, sqz 40 sx cement, displace to 1850 w/500 psi, WOC
Tag @ 1875, perf @ 420, sqz 40 sx cement, displace to 250, SION
07/20/00--Tag @ 243, pump 10 sx from surface to 60', RDMO
07/24/00--Cut off well head, install dry hole marker, cut off anchors, clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry McBeth TITLE Key energy P&A Supervisor DATE 07-24-00
TYPE OR PRINT NAME Terry McBeth TELEPHONE NO. (915) 523-5155

(This space for State Use)

APPROVED BY Johnny Robinson TITLE _____ DATE FEB 14 2001
CONDITIONS OF APPROVAL IF ANY C.W.W.