

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002520203
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-155
7. Lease Name or Unit Agreement Name New Mexico "O" State NCT-1
8. Well No. 19
9. Pool name or Wildcat Vacuum Glorieta

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
2. Name of Operator Texaco Producing Inc.	
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>2179</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>17-S</u> Range <u>34-E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4002' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Temporarily Abandoned ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

09-26-89 thru 10-11-89

- 1) MIRU PU. Unseated pmp. Hot oiled tbg & rods. TOH w/rods & pump. Instld BOP. TOH w/2-1/16" prod. tbg. TIH w/2-7/8" RBP & 2-1/16" tbg. Set RBP @ 5965'. Rel'd tbg. Tbg @ 5950'.
- 2) Test RBP to 1000 psi. Spt 100 gal. 10% Acetic acid across 2-7/8" casing 5439-5950'.
- 3) Perf'd 2-7/8" csg w/1 JSPI @ 5834-40,53-57,66,76,78,5932-38'. (22 holes).
- 4) A/perfs 5834-5938' w/3900 gal. 20% NEFE in 3 stgs w/250# RS blk btwn stgs. (Total 500# RS) Max P-3500#/Min P-0#. AIR 2.1 BPM. ISIP-200#. 15 min-0. Total ld 148 Bbls.
- 5) Rel'd & TOH w/2-7/8" pkr & 2-1/16" tbg. TIH w/2-1/16" tbg. Latched onto RBP & TOH w/RBP & 2-1/16" tbg. Instld pumping equip. Returned to prod. 09-30-89.
- 6) MIRU PU 10-11-89. TOH w/pmp laying dn rods. Instld BOP. TOH w/tbg. Rec. top conn of anchor. Junk @ 5644'.
- 7) TIH w/WS. TOH laying dn tbg. MIRU Rotary WL. RIH w/2-7/8" CIBP & set @ 5634'. Dumped 35' of cmt on top of plug. (East string) (OVER)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. A. Head TITLE Area Manager DATE 11/21/89
TYPE OR PRINT NAME J. A. Head TELEPHONE NO. (505)393-7191

(This space for State Use)

APPROVED BY Jerry Sexton ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

NOV 28 1989

DATE

CONDITIONS OF APPROVAL, IF ANY:

- 8) POH (West string). WIH w/2-7/8" guage ring to 5735'. POH. WIH w/CIBP & set @ 5734'.
Dumped 35' of cmt on top of plug.

Change of status from pumping to TA
Test Prior 24 BO, 32 BW.

RECEIVED

NOV 27 1989

OCN
FOBBS OFFICE