NE ÆXICO OIL CONSERVATION COMMISS N

SOUTHEAST NEW MEXICO PACKER LEAKAGE TEST

Operator	Leas			ell
Location Unit Sec	Twp	Mexico () State (County N	0. 23
of Well 0 36	Type of Prod	Method of Prod	, ,	Choke Size
Name of Reservoir or Pool	(Oil or Gas)	Flow, Art Lift	(Tbg or Csg)	Onore 512c
Compl Vacuum Chericia	0.7	Rod Pump	Cs,	
Compl Vacuum Khineley	AS	Dhold for space	ESING STYING	
,	FLOW TEST			
Both zones shut-in at (hour, date):_	13'40	7. 12. 71		
			Upper	Lower
Well opened at (hour, date): 12:15				Completion
Indicate by (X) the zone producing.				
Pressure at beginning of test	• • • • • • • • • • • • • • • • • • • •		····· <u>315</u>	120
Stabilized? (Yes or No)	•••••••	• • • • • • • • • • • • • • • • • • • •	<u>No</u>	<u>yes</u>
Maximum pressure during test	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • •	<u>315</u>	120
Minimum pressure during test	• • • • • • • • • • • • •	• • • • • • • • • • • • • • • • •	50	_120
Pressure at conclusion of test	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • •	90	120
Pressure change during test (Maximum				0
Was pressure change an increase or a				
		Total Tim	me On	
Well closed at (hour, date): 7'30 AA Oil Production	Gas Prod	d uc tion	on 21 hv: 15 A	
During Test: 93 bbls; Grav. 37.6	During 1	Test	MCF; GOR 298	
Remarks				
	FLOW TEST N	10. 2		_
Well opened at (hour, date):			Upper Completion	
Indicate by (X) the zone producing				
Pressure at beginning of test				
Stabilized? (Yes or No)				
Maximum pressure during test				
Minimum pressure during test				
Pressure at conclusion of test				
Pressure change during test (Maximum r	minus Minimum).	••••••	• • • • •	
Was pressure change an increase or a c	decrease?	m-1-7-1	• • • • •	
Well closed at (hour, date)		Total time Production	on	
Oil Production Ouring Test:bbls; Grav	Gas Produ ;During Te	at i an		
Remarks Blueby 2011 Shut in AS				
Annual zone Segregation To				
I hereby certify that the information cowledge.	herein contain	ed is true and con	mplete to the be	st of my
_		Operator 14xA	con INC.	
Approved] New Mexico Oil Conservation Commission	L9	Ву	I half	
			7	
itle		title ASST.		Supti
	L	ate 1-26-9	//	

SOUTHEAST NEW MEXICO PACKER LEAKAGE ' INSTRUCTIONS

- 1. A packer leakage test shall be commenced on the multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Commission.
- 2 At least 72 hours prior to the commencement of any packer leakage test, the operator shall actify the Commission in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3 The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized and for a minimum of two hours thereafter, provided however, that they need not remain shut-in more than 24 hours.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued until the flowing wellhead pressure has become stabilized and for a minimum of two hours thereafter, provided however that the flow test need not continue for more than 24 hours.

- 5. Pollowing comple of Flow Test No. 1, the well shall again be shutting in accordance with maragraph 3 above.
- 6 Flow Test No. 2 shall be conducted even hough no leak was instituted during Flow Test No. 1. Procedure for Flow fest No. 2 is to be the same as for Flow Test No. 1 except that the previously produced zone shall new mai, sput-in while the previously shut-in zone is produced.
- 7. All pressures, throughout the entire test, shall be continuously measured and re-orded with recording pressure gauges, the actimacy of which must be checked with a deadweight tester at least twice.once at the beginning and once at the end, of each flow test.
- beginning and shee at the end, of each flow test.

 8. The results of the above-described tests shall be filed in tripicate within 15 days after completion of the test. Tests shall be filed with the appropriate District Office of the New Mexico Oil Conservation Chamiston on Southeast New Mexico Packer Leakage Test Form Revised il-158, together with the original pressure recording gauge charts with all the descretiff the aforesaid charts, the operator may construct a pressure versus time curve for each zone of each test, indicating themson all pressure contages which may be reflected by the gauge charts as well as all deadwithing the source and charts which are taken. If the pressure curve is substituted, the original chart must be permanently filed in the operator's close to form C-116 shall also accompany the Packer Leakage Test Yora and the test period coincides with a gas-oil ratio test period.

	<u> </u>	
kangala a sama a kanasa kan sama sama sama kanasa kan		
		and the second s
pain agang dilippinning bakada		
		and the contract of the contra
)
₹ • • • • • • • • • • • • • • • • • • •		
		in the contract of the contrac
		the first transfer of the contract the contract transfer of the contrac
		in the contract of the contrac
		in the contract of the contrac
		in the contract of the contrac
		CEETVED.
		CEETVED.
		CEETVED.
		JUL 27 1971
		JUL 27 1971 OIL CONSERVATION COMM. HOBES, N. III.
		JUL 27 1971 OIL CONSERVATION COMM. HOBES, N. III.
		JUL 27 1971 OU CONSERVATION COMM. HORES, N. M.
		JUL 27 1971 OU CONSERVATION COMM. HOBES, N. M.
		JUL 27 1971 OU CONSERVATION COMM. HOBES, N. M.
		JUL 27 1971 OU CONSERVATION COMM. HOBES, N. M.
		JUL 27 1971 OU CONSERVATION COMM. HOBES, N. M.
		JUL 27 1971 OIL CONSERVATION COMML. HOBES, N. M.