

OIL CONSERVATION DIVISION

P O BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER- 2. Name of Operator SHELL OIL COMPANY 3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001 4. Location of Well UNIT LETTER <u>12</u> 2310 FEET FROM THE NORTH LINE AND 1980 FEET FROM THE EAST LINE, SECTION 31 TOWNSHIP 17-S RANGE 35-E N.M.P.M. 15. Elevation (Show whether DF, RT, GR, etc.) 3976' GL	7. Unit Agreement Name 8. Farm or Lease Name STATE "A" 9. Well No. 6 10. Field and Pool, or Wildcat VACUUM (GLORIETA) 12. County LEA
---	--

1c. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER OPEN ADDITIONAL PAY AND ACIDIZE <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
--	--	---	---

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Clean out to 6198' (PBSD).
2. Spot 200 gals 15% HCl-NEA across zone to be perf'd.
3. Perforate the Glorieta @ 6159', 6160', 6162', 6163', and 6165' (5 holes).
4. Acidized w/1000 gals 15% HCl-NEA. Acidize old perfs w/4200 gals 15% HCl-NEA.
5. Return well to production.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed <u>A. J. FORE</u> ORIGINAL SIGNED BY JERRY SEXTON DISTRICT SUPERVISOR	TITLE <u>SUPERVISOR REG. & PERMITTING</u>	DATE <u>JULY 20, 1982</u> <u>JUL 27 1982</u>
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY		