

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-1400	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator		8. Farm or Lease Name	
SHELL OIL COMPANY		STATE "T"	
3. Address of Operator		9. Well No.	
P. O. BOX 991, HOUSTON, TEXAS 77001		9	
4. Location of Well		10. Field and Pool, or Wildcat	
UNIT LETTER <u>I</u> , <u>2310</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>660</u> FEET FROM		VACUUM YATES	
THE <u>EAST</u> LINE, SECTION <u>33</u> TOWNSHIP <u>17-S</u> RANGE <u>35-E</u> NMPM.			
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
3938' GL		LEA	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>ABANDON VACUUM GLORIETA; RECOMPLETE</u> <input checked="" type="checkbox"/>	
		<u>IN VACUUM YATES POOL</u>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-10-83: Set 5-1/2" CIBP @ 3240' and capped w/35' of cmt. WOC 4 hrs. Tagged cmt @ 3204'.

11-14-83: Spotted 150 gals 15% NEA from 3,000' to 3150'. Perforated Yates formation 3043' to 3111' w/5,000 gals 15% NEA.

11-15-83: Installed production equipment.

11-16-83: Hooked up wellhead and flowline; returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. J. FORE A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE DECEMBER 5, 1983
ORIGINAL SIGNED BY EDDIE SEAY
APPROVED BY OIL & GAS INSPECTOR TITLE _____ DATE DEC 9 1983
CONDITIONS OF APPROVAL, IF ANY: _____

RECEIVED
DEC 8 1983
O.C.D.
HODGS OFFICE