

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	WELL API NO. 30-025-20334
2. Name of Operator Texaco Exploration & Production, Inc.	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator P. O. Box 3109, Midland, TX 79702	6. State Oil & Gas Lease No. B-1565
4. Well Location Unit Letter C : 660 feet from the North line and 1880 feet from the West line Section 36 Township 17S Range 34E NMPM Lea County	7. Lease Name or Unit Agreement Name: State BA
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. RIH Tag CIBP @ 5850' (Blinebry) on East side spot 105 Sx 5850'-1570' Tag @ 1718'
2. RIH Tag CIBP @ 5220' (San Andres) on West side spot 90 Sx 5220'-1570' Tag @ 1692'
3. Cut 2 7/8" Csg @ 1570' POH L/D both Csg Strings
4. RIH spot 125 Sx plug 1570'-1200' (T-Salt, 9 5/8" shoe) Tag @ 1173
5. Displace hole w/MLF, 9.5# Brine w/25# gel B/BBL
6. Circ Cmt 30' to Surf w/15 Sx, Install dry hole marker. 9/6/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER DATE 9/6/01
Type or print name Jimmy BAGLEY Telephone No. 915 683-4996
(This space for State use)

APPROVED BY Johnny Polina TITLE DATE OCT 18 2001
Conditions of approval, if any:

GWW

