| SANTA FE | DISTRIBUTI | | | NEW MEXICO OIL CONSERVATION COMMISSION (Form C-104) Santa Fe. New Mexico | | | | | |
|---|---|------------------------------------|--|--|---|---|-----------------------------------|---------------------------------------|--|
| FILE U.I.G.S. LAND OFFICE | | | · · · · · · · · · · · · · · · · · · · | REQUEST FO | OR (OIL) - (| (GAS) ALC | WABLE | | |
| TRANSPORTE PRORATION C | OIL GAS DFFICE | | | 4-OCC 1- | File | 0 AH '63 | | New Well Recompletion | |
| Thi Form C- able will month c | 104 is to be assign of compl | o be subr med effe letion or | nitted in Ç ctive 7:00 recomple | y the operator before an in QUADRUPLICATE to the A.M. on date of completion dates the reported on 15.025 r | initial allowable wi he same District O etion or recompleti ite shall be that da | III be assigned to a Office to which For ion, provided this ite in the case of a | m C-101 was so form is filed d | ent. The allow- luring calendar | |
| ered mit) the stock tanks. Oas must | | | | be reported on 15.025 psia at 60° Fahrenheit. Hobbs | | | | 9-26-63 | |
| | | | 0.110071 | | (Place) | NICHAINT AS. | | (Date) | |
| Tide | water | | GOH | NG AN ALLOWABLE State """ (Lea | , Well No | | in NE 1/4 | , | |
| | .C | | | , T 175 , R 34 1 | I, NMPM., . | Vacuum Bline | bry | | |
| | | | | County. Date Spudde Elevation | d. 6-1-63 | Date Drilling al Depth 6750 | g Completed | 6-26-63 | |
| Please indicate location: | | | | Top Oil/Gas Pay642 | | | | | |
| D | 7 ^C | В | A | 4409 84 . | - | | | 170-76; 6486-88; | |
| E | F | G | H | Perforations 6492-6 6658-61;6704-06 Open Hole | DS: 6583-343 Dep Cas | 6554-56; 6592 th sing Shoe6748 | Depth | | |
| L | K | J | I | OIL WELL TEST - Natural Prod. Test: | bbls.oil, | bbls water | inhrs, | Choke min. Size | |
| M | M N O P load oil used): <u>A</u> bbls,oil, <u>A</u> bbls water in <u>24</u> hr | | | | | | | Choke | |
| | | | | GAS WELL TEST - | | | | | |
| (FOOTAGE) | | | | Natural Prod. Test:MCF/Day; Hours flowedCh | | | | Size | |
| Tubing , Casing and Cementing Record Size Free Sax | | | | rd Method of Testing (pit Test After Acid or Fra | | | | flowed | |
| 9 5/8 1517 709 | | | 700 | Choke Size Method of Testing: 1000 gel. 15% acid. 20,000 gel. Ref. Crude. 12,250# 20-40 acid. | | | | | |
| 9 5/8 1517 2 7/8 6748 | | | Acid or Fracture Treats | ment (Give amounts | of materials used, | such as acid, w | water, oil, and | | |
| 27/ | 18 0 | 750 | *1667 | | | to tanks 9-2 | | | |
| | | | | Gil Transporter Texas New Mexico Pipe Line Co. | | | | | |
| | | | <u></u> | Gas Transporter | None | | | | |
| Remark | cs : | GC | <u>R 447/1</u> | Corr. Guty37.2 | Alma 200 | ····· | - | <u>- 1114 - 5</u> | |
| #B C | th-sta | inge (| of27/8 | ess. Completion in | Glorists-Blip | abry.zones. | | | |
| Th | s. is. | ertify th | Tubing I | ormation given above is | true and complete | to the best of my | knowledge. | | |
| Approv | nereby c red | | | , 19 | | | | ····· | |
| Арргоч | | | | | 01 | Original Signed By By: | | | |
| | OIL C | CONSEF | VATION | COMMISSION | By: | | | | |
| | 14 | M | | | Tiele | | | | |
| B y: | | <i>f</i> | ••••••••••••••••• | | Se | Title | | | |
| Title | | •••••••••• | ···· | | NameI | Box 249, Hobb | s, N. Mex. | | |
| | | | | | Adress | | | · · · · · · · · · · · · · · · · · · · | |