

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.  
**B-155-1**

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name -
2. Name of Operator <b>TEXACO Inc.</b>	8. Farm or Lease Name <b>New Mexico 'O' St. NCT-1</b>
3. Address of Operator <b>P.O. Box 728, Hobbs, New Mexico 88240</b>	9. Well No. <b>15</b>
4. Location of Well UNIT LETTER <b>I</b> <b>1800</b> FEET FROM THE <b>South</b> LINE AND <b>560</b> FEET FROM THE <b>East</b> LINE, SECTION <b>36</b> TOWNSHIP <b>17S</b> RANGE <b>34E</b> NMPM.	10. Field and Pool, or Wildcat <b>Vacuum Glorieta</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3,996' (DF)</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The following work has been completed on subject well:

1. Pulled rods and pump.
2. Drilled out CIBP at 5990'.
3. Perforated 2-7/8" casing w/2 JSPI @6055, 56, 60, 61, 62, 63, 64, 65, 74, 78, 87, 93 and 6108'. Perforated w/2 JSPF @ 6145-59'.
4. Ran drill pipe w/packer set at 6084'. Acidized w/250 gals 15% NEA. Ran 500# benzoic ~~flake~~ block. Acidized w/5000 gals 15% NEA in 2 - 2500 gal stages w/600# benzoic acid flakes between stages. Swab well.
5. Ran rods and pump, test and place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Joe D. Ratney* TITLE **Assistant District Superintendent** DATE **January 10, 1972**

APPROVED BY **Joe D. Ratney** TITLE **Dist. I, Supv.** DATE **JAN 12 1972**

CONDITIONS OF APPROVAL, IF ANY: