STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT					Form C-104		
	TAILUTION DIVISION					8 ·	
	SANTA FE, NEW MEXICO 87501						
UPENATON PLONATON PLONATON OFFICE	REQUEST FOI AI AUTHORIZATION TO TRANSI	ND		RAL GAS			
Operator Hondo Oil and Gas Compar	ny						
105 West 3rd, Suite 415		8201					
Reason(s) for filing (Check proper box) New Well Recompletion Change in Ownership		ry Gas ondensate	her (Flease Effect	explain) ive March 1, 1987			
f change of ownership give name hd address of previous owner							
Lease Name Mescalero Ridge Unit 35 2 Pearl Queen				Kind of Leuso Stato, Foderal or Foo Fe	d. NM	Lease No. 007465B	
Unit LotiorJ_: 198	0Feel From TheSouth_Lin	ne and <u>198</u>	30	Feel From TheEa	ist		
Line of Section 35 Town	whip 195 Range	34E	, нмрм	Lea		County	
III. DESIGNATION OF TRANSPORT		Address (Gi		to which approved copy of th			
Koch Oil Company Hund of Authorized Transporter of Cosinghead Gas ar Dry Gas			P. O. Box 1558, Breckenridge, TX 76024 Address (Give address to which approved copy of this form is to be sent) 4001 Penbrook, Odessa, Texas 79762				
Phillips 66 Natural Gas Company 1(well produces oil or liquids, give location of tonks. Unit Sec. Twp. Rge.			4001 Penbrook, Odessa, Texas 79762				
f this production is commingled with	that from any other lease or pool,	give commin	gling orde	r numberi			
NOTE: Complete Parts IV and V	on reverse side if necessary.	11			CION		
VI. CERTIFICATE OF COMPLIANCE thereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given is true and complete to the best of my knowledge and belief.			OIL CONSERVATION DIVISION				
			BYORIGINAL SIGNED BY JEPRY SEXTON DISTRICT SUPERVISOR				
Laipel Colly	2 ^j	If the well, this	le le s'req s form mue	be filed in compliance uset for allowable for a s t be accompanied by a to	nowly drilled obulation of	i or decrene the deviation	
Production Clerk			tests taken on the well in accordance with AULE 111. All sections of this form must be filled out completely for show- able on new and recompleted wells.				

Fill out only Sections 1. 11, 111, and VI for changes of Swasr. well name or number, or transporter, or other such change of condition.

March 27, 1987 (Duile)

Separate Forms C-104 must be filed for each pool in multiply completed wells.



~



·····.