

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
reverse side)E
reForm approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM - 0999A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Mescalero Unit

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Devonian Mescalero W/C

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

6-17-34

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

JUL 28 7 43 AM '64

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Humble Oil & Refining Company

3. ADDRESS OF OPERATOR

Box 2100, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface660 FNL, 1980 FEL, Sec. 6, T-19-S, R-34-E
NW/4 of NE/4 Sec. 6.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3845 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well plugged and abandoned. Plugs set as follows:

Plug #1 from 14,898 (TD) to 14,800 with 30 sxs cement.
Plug #2 from 13,100 to 13,000 with 40 sxs cement.
Plug #3 from 12,270 to 12,170 with 40 sxs cement.
Plug #4 from 9,100 to 9,000 with 40 sxs cement.
Plug #5 from 5,250 to 5,150 with 40 sxs cement.
Plug #6 from 50 to surface with 20 sxs cement.

Mud laden fluid between plugs. Dry hole marker installed per N. M. O. C. C.
requirements.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE 4-8-64

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

JUL 28 1964

DATE

J. L. GORDON

*See Instructions on Reverse Side