

August 16, 1978

Page 2

5. The produced fluids from these zones are currently commingled at the battery (Order No. PC-226, amended) and are known to be compatible. Since the oil is commingled at the surface, downhole commingling would not result in a reduction of oil value.
6. The ownership of the zones to be commingled is common.
7. Attached schematic diagrams of the wellbore showing the present completion and the proposed method of downhole commingling.
8. Downhole commingling will not jeopardize the efficiency of future secondary operations.
9. Copies of this application have been furnished to the offset operators.

Very truly yours,



C. S. Hilton, Jr.  
Operations Superintendent

AWR:mfm  
Enclosures

xc: Offset Operators  
Phillips Petroleum Company  
Phillips Building  
4th & Washington  
Odessa, Texas 79761

Mobil Oil Corporation  
P. O. Box 633  
Midland, Texas 79701

Getty Oil Company  
P. O. Box 1231  
Midland, Texas 79701

Shell Oil Company  
P. O. Box 1509  
Midland, Texas 79701

RECEIVED

AUG 11 1978

INVESTIGATION COMM  
FBI - MEMPHIS