NO. OF COPIES RECEIVED	-1		
DISTRIBUTION			Form C-103 Supersedes Old
NTAFE		INSERVATION COMMISSION	C-102 and C-103
LE		MISER A LION COMMISSION	Effective 1-1-65
.G.S.	1		Sa. Indicate Type of Lease
ND OFFICE	-		
ERATOR	-1	•	
			5. State Off 6 Gas Leave No.
		·	387
DO NOT USE THIS FORM FOR PO	RY NOTICES AND REPORTS OF THE AND THE PORTS OF THE PRIME TO SERVICE AND THE PORTS OF PLUT	DN WELLS	
OSE TAPPLICA	TION FOR FIRMET -** (FOPM C-101) FOR	SUCH PROPOSALS.)	
OIL X CAS WELL	OTHER-Triple (Abo-Wolf	Camp-Hoper Penn)	7. Unit Agreement Manie
ame of Operator		rent opport tenni	8. Furm or Lease Name
Marathon Oil Company			
liress of Operator			<u>Warn State a/c 1</u> 9. Well No.
P. O. Box 2409	Hobbs, New Mexico 882	240	1 0
cation of Well	100000, 1000 Healed 002		3
F	2080 North	1000	10. Field and Pool, or Wildcut
UNIT LETTER F	2080 FEET FROM THE North	LINE AND FEI	T FROM Vacuum
	•		777777777777777777777777777777777777777
THE West LINE, SECTION	ON 31 TOWNSHIP 17	S 8ANGE 35E	
THUITHIN MARKEN IN THE			
	15. Elevation (Show wheth	-	12. County
	<u>      GL 3975'; KDB</u>	<u>3989'</u>	Lea
Check ,	Appropriate Box To Indicate	Nature of Notice Report	
NOTICE OF IN	NTENTION TO:		
		SUBSEC	UENT REPORT OF:
ORM REMEDIAL WORK	PLUG AND ABANDON	1	
ORARILY ABANDON	, FLOG ARE ABARDON [	KEMEDIAL WORK	ALTERING CASING
OR ALTER CASING	· · · · ·	COMMENCE DRILLING OPNS.	PLUG AND ABANDONISENT
	CHANGE PLANS	CASING TEST AND CEMENT JOB	
THER		OTHER I PE CASING D.	radenheads to surface
		11	
		1	
	erations (Clearly state all pertinent de	J	And in the second s
	erations (Clearly state all pertinent de	uails, and give pertinent dates, inc	luding estimated date of starting ony propose
	erations (Clearly state all pertinent de	tails, and give pertinent dates, inc	luding estimated date of starting ony propose
escribe Proposed or Completed Op orkj SEE RULE 1 f03.	•		huding estimated date of starting any propose
escribe Proposed or Completed Op orkj SEE RULE 1 f03.	erations (Clearly state all pertinent de to expose all casing bu		Inding estimated date of starting any propose
escribe Proposed or Completed Op ork) SEE RULE 1 fo3. Dug well cellar out	to expose all casing by	radenhead outlets.	· · ·
Dug well cellar out Installed 1" piping	to expose all casing by from 2" value on outlet	radenhead outlets.	· · ·
Dug well cellar out Installed 1" piping	•	radenhead outlets.	· · ·
Dug well cellar out Installed 1" piping level. Installed 1	to expose all casing by from 2" valve on outled " valve on upper end of	radenhead outlets. t on each bradenhead f piping.	· · ·
escribe Proposed or Completed Op ork) SEE RULE 1 fo3. Dug well cellar out Installed 1" piping level. Installed 1'	to expose all casing by from 2" valve on outled " valve on upper end of	radenhead outlets. t on each bradenhead f piping.	· · ·
escribe Proposed or Completed Op ork) SEE RULE 1 fo3. Dug well cellar out Installed 1" piping level. Installed 1 Ran bradenhead press	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated	radenhead outlets. t on each bradenhead m piping. no leak.	to a point above ground
escribe Proposed or Completed Op ork) SEE RULE 1 fos. Dug well cellar out Installed 1" piping level. Installed 1' Ran bradenhead press Piping arrangement,	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val	radenhead outlets. t on each bradenhead f piping. no leak.	to a point above ground
escribe Proposed or Completed Op ork) SEE RULE 1 103. Dug well cellar out Installed 1" piping level. Installed 1" Ran bradenhead press Piping arrangement, and approved by New	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val	radenhead outlets. t on each bradenhead f piping. no leak.	to a point above ground
escribe Proposed or Completed Op ork) SEE RULE 1 fos. Dug well cellar out Installed 1" piping level. Installed 1' Ran bradenhead press Piping arrangement,	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated	radenhead outlets. t on each bradenhead f piping. no leak.	to a point above ground
escribe Proposed or Completed Op ork) SEE RULE 1 fos. Dug well cellar out Installed 1" piping level. Installed 1' Ran bradenhead press Piping arrangement, and approved by New	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val	radenhead outlets. t on each bradenhead f piping. no leak.	to a point above ground
escribe Proposed or Completed Op ork) SEE RULE 1 103. Dug well cellar out Installed 1" piping level. Installed 1" Ran bradenhead press Piping arrangement, and approved by New	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val	radenhead outlets. t on each bradenhead f piping. no leak. tve and closed position Commission Deputy Of	to a point above ground
escribe Proposed or Completed Op ork) SEE RULE 1 fos. Dug well cellar out Installed 1" piping level. Installed 1' Ran bradenhead press Piping arrangement, and approved by New	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation	radenhead outlets. t on each bradenhead f piping. no leak. tve and closed position Commission Deputy Of Bradenhead	to a point above ground on of 1" valve, inspected 11 and Gas Inspector,
escribe Proposed or Completed Op ork) SEE RULE 1 fos. Dug well cellar out Installed 1" piping level. Installed 1' Ran bradenhead press Piping arrangement, and approved by New	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation	radenhead outlets. t on each bradenhead f piping. no leak. tve and closed position Commission Deputy Of Bradenhead <u>Valve Location (1</u>	to a point above ground on of 1" valve, inspected 11 and Gas Inspector,
escribe Proposed or Completed Op ork) SEE RULE 1 103. Dug well cellar out Installed 1" piping level. Installed 1" Ran bradenhead press Piping arrangement, and approved by New	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation <u>Bradenhead Size</u> 13-3/8"	radenhead outlets. t on each bradenhead f piping. no leak. tve and closed position Commission Deputy Of Bradenhead	to a point above ground on of 1" valve, inspected 11 and Gas Inspector,
Dug well cellar out Installed 1" piping level. Installed 1 Ran bradenhead press Piping arrangement, and approved by New	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation	radenhead outlets. t on each bradenhead f piping. no leak. tve and closed position Commission Deputy Of Bradenhead <u>Valve Location (1</u>	to a point above ground on of 1" valve, inspected 11 and Gas Inspector, <u>")</u>
Dug well cellar out Installed 1" piping level. Installed 1 Ran bradenhead press Piping arrangement, and approved by New	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation <u>Bradenhead Size</u> 13-3/8"	radenhead outlets. t on each bradenhead f piping. no leak. tve and closed position Commission Deputy Of Bradenhead <u>Valve Location (1</u> Southeast side of	to a point above ground on of 1" valve, inspected 11 and Gas Inspector, <u>")</u>
Dug well cellar out Installed 1" piping level. Installed 1 Ran bradenhead press Piping arrangement, and approved by New	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation <u>Bradenhead Size</u> 13-3/8"	radenhead outlets. t on each bradenhead f piping. no leak. tve and closed position Commission Deputy Of Bradenhead <u>Valve Location (1</u> Southeast side of	to a point above ground on of 1" valve, inspected 11 and Gas Inspector, <u>")</u>
Dug well cellar out Installed 1" piping level. Installed 1 Ran bradenhead press Piping arrangement, and approved by New Nathan Clay.	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation <u>Bradenhead Size</u> 13-3/8" 9-5/8"	radenhead outlets. t on each bradenhead a piping. no leak. tve and closed position Commission Deputy Of Bradenhead <u>Valve Location (1</u> Southeast side of East side of well	to a point above ground on of 1" valve, inspected 11 and Gas Inspector, <u>")</u>
escribe Proposed or Completed Cp ork) SEE RULE 1703. Dug well cellar out Installed 1" piping level. Installed 1" Ran bradenhead press Piping arrangement, and approved by New Nathan Clay.	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation <u>Bradenhead Size</u> 13-3/8"	radenhead outlets. t on each bradenhead a piping. no leak. tve and closed position Commission Deputy Of Bradenhead <u>Valve Location (1</u> Southeast side of East side of well	to a point above ground on of 1" valve, inspected 11 and Gas Inspector, <u>")</u>
escribe Proposed or Completed Op ork) SEE RULE 1703. Dug well cellar out Installed 1" piping level. Installed 1' Ran bradenhead press Piping arrangement, and approved by New Nathan Clay.	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation <u>Bradenhead Size</u> 13-3/8" 9-5/8"	radenhead outlets. t on each bradenhead a piping. no leak. tve and closed position Commission Deputy Of Bradenhead <u>Valve Location (1</u> Southeast side of East side of well	to a point above ground on of 1" valve, inspected 11 and Gas Inspector, <u>")</u>
Dug well cellar out Installed 1" piping level. Installed 1 Ran bradenhead press Piping arrangement, and approved by New Nathan Clay.	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation <u>Bradenhead Size</u> 13-3/8" 9-5/8"	radenhead outlets. t on each bradenhead f piping. no leak. tve and closed position Commission Deputy Of Bradenhead <u>Valve Location (1</u> Southeast side of East side of well	to a point above ground on of 1" valve, inspected 11 and Gas Inspector, ") well
escribe Proposed or Completed Op ork) SEE RULE (103. Dug well cellar out Installed 1" piping level. Installed 1' Ran bradenhead press Piping arrangement, and approved by New Nathan Clay.	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation <u>Bradenhead Size</u> 13-3/8" 9-5/8"	radenhead outlets. t on each bradenhead a piping. no leak. tve and closed position Commission Deputy Of Bradenhead <u>Valve Location (1</u> Southeast side of East side of well	to a point above ground on of 1" valve, inspected 11 and Gas Inspector, <u>")</u>
Dug well cellar out Installed 1" piping level. Installed 1 Ran bradenhead press Piping arrangement, and approved by New Nathan Clay.	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation <u>Bradenhead Size</u> 13-3/8" 9-5/8"	radenhead outlets. t on each bradenhead f piping. no leak. tve and closed position Commission Deputy Of Bradenhead <u>Valve Location (1</u> Southeast side of East side of well	to a point above ground on of 1" valve, inspected 11 and Gas Inspector, (") well well
escribe Proposed or Completed Op ork) SEE RULE 1703. Dug well cellar out Installed 1" piping level. Installed 1' Ran bradenhead press Piping arrangement, and approved by New Nathan Clay.	to expose all casing by from 2" valve on outled " valve on upper end of sure. Survey indicated open position of 2" val Mexico Oil Conservation <u>Bradenhead Size</u> 13-3/8" 9-5/8"	radenhead outlets. t on each bradenhead f piping. no leak. tve and closed position Commission Deputy Of Bradenhead <u>Valve Location (1</u> Southeast side of East side of well	to a point above ground on of 1" valve, inspected 11 and Gas Inspector, ") well well