

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 20778
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-2317
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	84
9. Pool Name or Wildcat	VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4002'	

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER HORIZONTAL LATERAL ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter I 560 Feet From The EAST Line and 2080 Feet From The SOUTH Line Section 35 Township 17S Range 34E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4002'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: HORIZONTAL LATERAL ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-25-98: MIRU.
6-26-98: TOH W/2 3/8" TBG. SLM @ 5629'. TIH W/CSG SCRAPER & BIT. TIH W/GAUGE RING W/JNK BSKT TO 6000' FOR CCL LOG. TIH W/CIBP & SET @ 5806'. TIH W/2 3/8" TBG TO 5629'.
6-27-98: TIH W/5 JTS TO 5796'. TOH W/TBG. LD 160 JTS. SET PKR. PMP DN TBG. PKR @ 310'. RUN CSG INSP LOG FR 5806-4700' & 1300-1000'.
6-28-98: NDBOP. INSTL NEW SEAL. PSI TEST CSG, BOPS & FLANGES. NO LEAKS.
6-30-98: RU DRLG OPERATIONS. UNLOAD DP W/CONNECTIONS. HU FLOWLINE. TIH W/MILLS. TOH W/DP. TIH W/WHIPSTOCK.
7-01-98: RU WIRELINE EQPT FOR GYRO. RU GYRO. TOH W/DP. TIH W/CSG MILL.
7-02-98: DRILLING. TD @ 6727' @ 12:45 AM 7-05-98.
7-06-98: LD RBP. TIH & SET RBP @ 5000'. PRESS TEST TO 500 PSI-OK. LDDP. R G DOWN.
7-09-98: UNLOAD 2 3/8" TBG. PU RETR HEAD & TIH TO 5000'. REL RBP @ 5000'. PU 2 JTS 2 3/8" TBG & PKR.
7-10-98: TIH W/TBG. RAN PKR & SET @ 5758.78'. RE-ENTRY GUIDE @ 5832.40' KB. NU TREE & PSI TEST CSG TO 700#.
7-14-98: INSTL SENSOR ON COIL TBG. TIH W/TBG TO 6712'. CIRC 1000 GALS 15% HCL ACR FORM. CIRC OUT ACID.
7-15-98: OPEN WELL ON 8/64 CHOKE & FLOW WELL TO TEST TANK.
7-16-98: REL PKR & PULL TBG.
7-18-98: FLOW TBG TO TANK UNTIL DIED. ND FRAC TREE. REL PKR. TOH & LD PKR. TIH W/15 STD KILL STRING.
7-19-98: TIH W/12 STD & SET RBP @ 750'. NDBOP & DRLG FLANGE. NU TBG HD & BOP. TIH & REL RBP. TIH W/SUB PUMPS & MOTOR ON 2 3/8" TBG. SET PUMP @ 5736'. NDBOP. NU WELL. CONNECT ELEC & NU TO FLOW LINE. WELL ON PUMP @ 6:00 PM.
7-21-98: ON 24 HR OPT. PUMPED 315 BO, 516 BW, & 62 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 7/31/98
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: