



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
HOBBS DISTRICT OFFICE

BRUCE KING
GOVERNOR
LARRY KEHOE
SECRETARY

September 13, 1979

POST OFFICE BOX 1860
HOBBS, NEW MEXICO 88240
(505) 393-6161

Mr. Bill Durham
Phillips Petroleum Company
4001 Penbrook
Odessa, Texas 79762

SUBJECT: Division Order R-5897

Gentlemen:

After re-examining the additional information submitted, it has been determined that the following wells appear to have the Grayburg-San Andres zone properly cemented off:

Phillips Petroleum Company

Vacuum Abo Unit Tr. 7 Well #4-I in Section 27, T17S, R35E
Additional information -- DV collar at 4606 feet

Vacuum Abo Unit Tr. 13 Well #2-E in Section 4, T18S, R35E
Additional information -- DV collar at 4986 feet

Vacuum Abo Unit Tr. 7 Well #3-P in Section 27, T17S, R35E
Additional information -- DV collar at 4654 feet

EVGSAU Tr. 2865 Well #002-G in Section 28, T17S, R35E
Additional information -- Temperature survey showed top of cement above GB

✓ EVGSAU Tr. 2717 Well #006-P in Section 27, T17S, R35E
Additional information -- Bond log showed bonding above GB 3910--3950'

EVGSAU Tr. 2851 Well #001-A in Section 28, T17S, R35E
Additional information -- Record of temperature log in OCD files showed top of cement above GB

The following well will still need to be re-entered as there is no cement top available for the 4½" casing, and there is no solid plug between the top of the salt and surface: Amoco, State CV Well #1-L in Section 25, T17S, R35E.

Very truly yours,

OIL CONSERVATION DIVISION

Jerry Sexton, Supervisor, Dist. I

JS/ed

cc: Joe D. Ramey - OCD Santa Fe
R.L. Stamets - OCD Santa Fe