- 1-18-69: Moved in work-over Rig, commenced working operations at 8 AM on 1-18-69. Fished out rods, ran swb, found fluid level standing at 6000' below surface. Swb well for 2 hrs. Fluid level standing at 7000' below surface after 2 hr swb test.
- 1-19-69: Shut in.
- 1-20-69: Attempted to unseat anchor catcher @ 10,000'. Unable to release. Tried to shear pins. Couldn't move tbg; worked tbg until 3 PM. Pumped 45 bbls wtr into csg & filled up approx 4500', csg stands full. Prep to free point tbg.
- 1-21-69: Attempted to release tbg anchor after putting fresh wtr into csg. Unable to release. Ran Homco Freepoint. Tbg free @ SN 10,049' KB. Ran chemical cutter tool & cut off tbg @ 10,033' KB, leaving 15' tbg SN & anchor catcher w/mud anchor in hole. Pulled tbg & put on spear, jars & drill collars. Going in hole w/tbg.
- 1-22-69: Ran rest of tbg, caught fish & jarred for 35". Spear came out of fish, unable to keep hold. Pulled tbg & put on overshot (3 7/8" OD). Going into hole w/tbg. Hit obstruction in csg @ 7731' KB. Tbg wouldn't go down. Pumped 130 bbls fresh wtr down tbg & worked pipe didn't make any hole. Shut in & let wtr set until morning.
- 1-23-69: Unable to get overshot below 7731' after wtr standing in csg overnight. Pulled tbg w/over-shot. Ran back w/3 7/8" bit. Worked tbg down to top of fish. Pulled tbg w/bit. Running tbg w/1 jt washpipe & clustrite shoe. Prep to wash down & mill over anchor.
- 1-24-69: Ran tbg w/wash pipe. Tagged fish put on Kelly & broke circulation. Washed down 16' to anchor. Fish turned loose & pushed to bottom. Top @ 10,186' KB. Pulled tbg. Prep to squeeze perfs.
- 1-25-69: Ran tbg w/RTTS squeeze tool. Set @ 9921' KB. Est inj rate @ 2 bbl per min. @ 3800 PSI. Pumped 75 sx class "C" cmt w/1% fluid loss & friction reduce additive. Unable to get squeeze to hold. Cleaned perfs @ 10,140 10, 176'. Unable to pump w/any rate @ 5000 PSI. Unseat pkr & reverse out. Washed down through perfs w/tbg trying to open formation. Pulled pkr up & set @ 9900'. Press up to est inj rate again. Same as before. Shut in overnight. (No cmt was reversed out).
- 1-26-69: Ran tbg down thru perfs & spotted 200 gal 15% NE acid. Set pkr @ 9900'.

 Press built to 5500#, bled off to 5200# in 2 min. Couldn't get formation to break. Reversed out acid & pulled tbg. Prep to perf.
- 1-27-69: Western Co. perf @ 10,142' 10,150' w/2 3/8" JS/F. Ran tbg w/RTTS pkr Spotted acid across perfs. Set pkr @ 10,074'. Started breakdown, csg & tbg comm. Reset pkr @ 10,044'. Acidized w/2000 gal 15% spearhead acid, using ball sealers. Max press 5000#, break to 4400#, aver treat press 4600#, ISIP 3500#, 20 min SIP 3100#, aver inj rate 2.3 BPM, total load 132 bbls wtr. Ran Western Co. Tracer Survey. Some fluid going to 10,176' no lower. Fluid going into perfs 10,142 10,150' and going up hole. Checked @ 10,020'. Still moving up. Shut in until morning.