

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Enc. 6, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-20942
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator Prize Operating Company		6. State Oil & Gas Lease No. B-1722-1
3. Address of Operator 3500 William D. Tate, Suite 200, Grapevine, Texas 76051		7. Lease Name or Unit Agreement Name: New Mexico 'N' State
4. Well Location Unit Letter L : 460 feet from the West line and 1980 feet from the South line Section 30 Township 17S Range 35E NMPM County Lea		8. Well No. 6
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4003' DF		9. Pool name or Wildcat Vacuum, Abo North

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Prize Operating Company respectfully request approval to Temporarily Abandon the Vacuum, Abo North zone of this triple completion well. Texaco is the operator of the other two zones. The following procedure is submitted for approval:

1. MURU workover rig. Blow down Abo 2 7/8" production string.
2. Rig up pump truck and pressure test 2 7/8" tubing to 500# for 15 minutes.
3. Rig down truck and leave zone TA'd

Attached is a Sundry notice filed by Texaco identifying placement of a 2 7/8" CIBP in the Abo production string (approved by the OCD on 3-4-88).

Also attached is wellbore schematic.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Don Aldridge TITLE Regulatory Analyst DATE 10-17-2001

Type or print name Don Aldridge Telephone No. 817-424-0454

(This space for State use)

APPROVED BY _____ TITLE _____ DATE 10-17-2001
Conditions of approval, if any: _____


5
C

**State of New Mexico "N" Well #6
T & A Wellbore**

Procedure:

1. MIRU Workover Rig. Blow down North Abo 2 7/8" production string.
2. Rig up pump truck and pressure test 2 7/8" tubing to 500# for 15 minutes.
3. RDMO. Well is TA'd.

Note: 2-7/8" casing cemented with 600 sx Class "C", 2% gel, and 1200 sx Class "C", 4% gel. Cement volume equals 195% of annular space from TD to int. casing



LEASE: State of New Mexico "N" Well No. 6
FIELD: Vacuum (Glorieta, North Abo and Wolfcamp)
DATE: July 24, 1964

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES DESIRED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2000

SANTA FE, NEW MEXICO 87501

Form O-1
Revised 1

2a. Interest Type of Lease	State ☒ Fed ☐
2b. State Oil & Gas Lease No.	55382

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPERATE OR PLUG BACK TO A DIFFERENT WELL. USE APPLICATION FOR PERMIT - A - WHICH COLLECTS THE PROPOSAL.

1. ☒ ON WELL ☐ OFF WELL ☐ OTHER	7. State Department Stamp
2. Name of Operator Texaco Producing Inc.	8. Name of Lease Name Nm "N" State
3. Address of Operator P.O. Box 728 Hobbs, NM 88240	9. Well No. 6
4. Location of Well NE 1/4 L 1980 FEET FROM THE South LINE AND 460 FEET FROM the West LINE, SECTION 30 TOWNSHIP 17-S RANGE 35-E	10. Field and Pool, or Well Vacuum Glorieta, Abo and Wolfcamp
11. Elevation (Show whether DF, RT, GR, etc.) 4003' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER Casing ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

REMEDIAL WORK ☐

PLUG AND ABANDON ☐

Shut off Abo and Wolfcamp

17. Describe Procedure or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop
work/ SEE RULE 1702.

1. MIRV pulling unit on 2-2-87. Set 2 7/8" CIBP in y-string (Abo) at 8975' and dumped 35' cement on top. PBTD = 8940'. This shuts off Abo perfs at 9079-9214'
2. Set 2 7/8" CIBP at 6325' in z string (Wolfcamp) and dumped 35' cement on top. PBTD = 6290'. This shuts off Wolfcamp perfs 9612-9833' (fish in hole, top = 6328').

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

by A. Gernandt
A. Gernandt 393-4031
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

by Area Superintendentdate 3-1-88

MAR 4 - 1988