

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 04214

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR William G. Ross	7. UNIT AGREEMENT NAME
3. ADDRESS OF OPERATOR P. O. Box 86, Midland, Texas 79701	8. FARM OR LEASE NAME Federal "WR"
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FSL & 990' FWL	9. WELL NO. 1
14. PERMIT NO.	10. FIELD AND POOL, OR WILDCAT Quercho Plains Penn
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3810 KBM	11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec 15-T18S-R32E
	12. COUNTY OR PARISH Lea
	13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Spotted a 45 sx cement plug at 8650'.
2. Spotted a 40 sx cement plug at 5½ casing stub at 8010'.
3. Spotted a 30 sx cement plug at 4700'-4600'.
4. Spotted a 35 sx cement plug at 9-5/8" casing shoe at 4100'.
5. Spotted a 35 sx cement plug at 9-5/8 casing stub at 2500'.
(50' In & 50' Out)
6. Spotted a 35 sx cement plug at 13-3/8 casing shoe at 875'.
(50' In & 50' Out)
7. Spotted a 15 sx cement plug at surface with marker.
8. Hole was loaded with mud-laden fluids.
9. Well was plugged and abandoned on 5/1/71.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 5/5/71

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
SEP 13 1971ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED

OCT - 11971

OIL CONSERVATION COMM.
HOBBS, N. M.