

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-1578	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. <u>Dual</u> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Atlantic Richfield Company	
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201	
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1800</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>17-S</u> RANGE <u>35-E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 3991' GR	

7. Unit Agreement Name
8. Farm or Lease Name State "B" 1578
9. Well No. 3
10. Field and Pool, or Wildcat Vacuum-Glorieta/Wfd
12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> Wolfcamp	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Recomplete in Abo Zone
SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Wolfcamp zone production in this dual well has declined to less than 2 BOPD, no water & no remedial possibilities exist. We propose to P & A Wolfcamp by setting a DR plug in 415-D packer at 9700' & capping w/2 sx of cement. Recomplete in Abo by perforating w/1 1/2" JS @ 8469, 8476, 8489, 8504, 8522, 8528, 8540, 8550, 8560, 8577, 9098, 9136, 9148, 9157, 9166, 9181, 9198, 9210, 9226 & 9244 (20 holes) & treating w/4000 gal of 15% HCl acid. Treat existing Glorieta perfs 6082-6139 w/1000 gal 15% HCl acid. Set 415-D packer at about 8400' & run 2-3/8" tubing for Abo zone. Land 2-3/8" tubing at about 6150' for Glorieta zone.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>[Signature]</u>	TITLE <u>Dist. Drlg. Supervisor</u>	DATE <u>10/22/71</u>
APPROVED BY <u>[Signature]</u>		
CONDITIONS OF APPROVAL, IF ANY:		
TITLE <u>DISTRICT I</u> DATE <u>10 26 1971</u>		

RECEIVED

OCT 20 1971

**OIL CONSERVATION COMM.
HOBBBS, N. H.**