and The second house an and a second	na an inclusion and an	an a	مى مى يې
د محموله در این این این این این این محمولیت در این محمولیت و موجه محمولیت و محمولیت که ۲۰۰۰. محمولیت با در این این این این محمولیت محمولیت محمولیت و محمولیت محمولیت محمولیت محمولیت که ۲۰۰۰ محمولیت که ۲۰۰	میں این وہیں دار میں بادی میں کری کی ایک ایک میں میں میں ایک ایک ایک ایک ایک میں میں ایک ایک ایک ایک ایک ایک ای ایک ایک میں میں ایک	names er a son de daaren oor aan aan aan waar waar de	
NO. OF COMIES RECEIVED			
DISTRIBUTION	NEW MEXICO OIL	CONSERVATION COMMISSION	Form C-104
SANTA FE	REQUEST	FOR ALLOWABLE	Supersedes Old C-10; and C-110
FILE		AND	Effective 1-1-65
U.S.G.S.	AUTHORIZATION TO TR	ANSPORT OIL AND NATURAL C	SAS
LAND OFFICE			
TRANSPORTER GAS			
OPERATOR		•	
I. PRORATION OFFICE		• .	·
Operator ARCO Oil and (tlantic Richfield Company		. •
Address	clantic Richifeld Company		
	, Hobbs, New Mexico 8824	0	
Reason(s) for filing (Check proper		Other (Please explain)	
New Well	Change in Transporter of:	Change in Operat	
Recompletion			79
Change in Ownership	Casinghead Gas Conde		
If change of ownership give name	e		
and address of previous owner			
IL DESCRIPTION OF WELL AN			
Lezse Name	Well No. Fool No	ame, Including Formation	Kind of Lease
State L DE	2 /22	uum Glorieta	State, Federal or Fee State
Unit Letter (7 ; 4	3/0 Feet From The Mouth	ne and2310Feet From '	The <u>fast</u>
Line of Section 30	Township (75 Range	35E , NMPM,	la County
			county
II. DESIGNATION OF TRANSPO	RTER OF OIL AND NATURAL GA	<u> </u>	
Name of Authorized Transporter of		Address (Give address to which approv	
10/00 New-Mexico	Casinghead Gas or Dry Gas	P.O. Box 1510 mall	and, Texas 19701
Phillip Pathe		the interest of the second	1210, Texas 79762
If well produces oil or liquids,	Unit Sec. Twp. Pge.	Is gas actually connected?	
TH WELL FIGURES OU OF HERMS.			· · · · · · · · · · · · · · · · · · ·
It well produces oil or liquids, give location of tanks.	G : 30 175 35E	Yes	Unprocon
give location of tanks.	G 130 175 35E with that from any other lease or pool,	1	Unbuown
give location of tanks.	with that from any other lease or pool,	give comminging order number:	
give location of tanks. If this production is commingled	with that from any other lease or pool,	1	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA	with that from any other lease or pool,	give comminging order number:	
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple	with that from any other lease or pool, tion - (X)	give commingling order number:	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded	with that from any other lease or pool, tion - (X)	give commingling order number:	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool	with that from any other lease or pool, tion - (X) Off Well Gas Well Date Compl. Ready to Prod.	give commingling order number:	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change	with that from any other lease or pool, tion - (X) Off Well Gas Well Date Compl. Ready to Prod.	give commingling order number:	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool	with that from any other lease or pool, tion - (X) Oil Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool	with that from any other lease or pool, tion - (X) OII Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations	with that from any other lease or pool, tion - (X) Oil Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations	with that from any other lease or pool, tion - (X) OII Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations	with that from any other lease or pool, tion - (X) OII Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations HOLE SIZE	with that from any other lease or pool, ition	give commingling order number: New Well Workover Deepen Total Depth Top OU/Gas Pay D CEMENTING RECORD DEPTH SET	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations HOLE SIZE /. TEST DATA AND REQUEST	with that from any other lease or pool, ition - (X) OII Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET fter recovery of total volume of load oil	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations HOLE SIZE	with that from any other lease or pool, ition - (X) OII Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a	give commingling order number: New Well Workover Deepen Total Depth Top OU/Gas Pay D CEMENTING RECORD DEPTH SET	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations HOLE SIZE /. TEST DATA AND REQUEST OIL WELL Date First New Oll Run To Tanks No Change	with that from any other lease or pool, Oll Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET fter recovery of total volume of load oil epth or be for full 24 hours)	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations HOLE SIZE	with that from any other lease or pool, Oll Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET fter recovery of total volume of load oil epth or be for full 24 hours)	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool HOLE SIZE Image: Pool Image: Pool Perforations Image: Pool Designate Type of Complete Date Spudded No Change Image: Pool Image: Pool Perforations Image: Pool Perforations Image: Pool Perforations Pe	with that from any other lease or pool, ition - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET filer recovery of total volume of load oil epth or be for full 24 hours) Producing Method (Flow, pump, gas li Casing Pressure	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT SACKS CEMENT
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations HOLE SIZE /. TEST DATA AND REQUEST OIL WELL Date First New Oll Run To Tanks No Change	with that from any other lease or pool, ition (X) Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET DEPTH SET fter recovery of total volume of load oil epth or be for full 24 hours) Producing Method (l'low, pump, gas li)	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool HOLE SIZE Image: Pool Image: Pool Perforations Image: Pool Designate Type of Complete Date Spudded No Change Image: Pool Image: Pool Perforations Image: Pool Perforations Image: Pool Perforations Pe	with that from any other lease or pool, ition - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET filer recovery of total volume of load oil epth or be for full 24 hours) Producing Method (Flow, pump, gas li Casing Pressure	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow- (t, etc.) Choke Size
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool HOLE SIZE Image: Pool Image: Pool Perforations Image: Pool Designate Type of Complete Date Spudded No Change Image: Pool Image: Pool Perforations Image: Pool Perforations Image: Pool Perforations Pe	with that from any other lease or pool, ition - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET filer recovery of total volume of load oil epth or be for full 24 hours) Producing Method (Flow, pump, gas li Casing Pressure	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow- (t, etc.) Choke Size
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations HOLE SIZE 	with that from any other lease or pool, ition - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET filer recovery of total volume of load oil epth or be for full 24 hours) Producing Method (Flow, pump, gas li Casing Pressure	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow- (t, etc.) Choke Size
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool HOLE SIZE HOLE SIZE Image: Date Spudded HOLE SIZE HOLE SIZE Image: Date Spudded No Change Length of Test Actual Prod. During Test GAS WELL Actual Prod. Test-MCF/D	with that from any other lease or pool, with that from any other lease or pool, I OII Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure QII-Bbis. Length of Test	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET for recovery of total volume of load oil epth or be for full 24 hours) Producing Method (Flow, pump, gas li, Casing Pressure Water-Bbls.	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT SACKS CEMENT Choke Size Gas-MCF
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations HOLE SIZE 	with that from any other lease or pool, ition (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure OII-Bbls.	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET for recovery of total volume of load oil epth or be for full 24 hours) Producing Method (Flow, pump, gas li, Casing Pressure Water-Bbls.	Plug Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations HOLE SIZE Image: Hold Size Pool Perforations Image: Hold Size Pool Image: Hold Size Imag	with that from any other lease or pool, with that from any other lease or pool, I OII Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, ANI CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure QII-Bbls. Length of Test Tubing Pressure	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET DEPTH SET for recovery of total volume of load oil epth or be for full 24 hours) Producing Method (Flow, pump, gas li, Casing Pressure Water-Bbls. Bbls. Condensate/MMCF Casing Pressure	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT SACKS CEMENT and must be equal to or exceed top allow- (t, etc.) Choke Size Gas-MCF Gravity of Condensate Choke Size
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool HOLE SIZE HOLE SIZE Image: Date Spudded HOLE SIZE HOLE SIZE Image: Date Spudded No Change Length of Test Actual Prod. During Test GAS WELL Actual Prod. Test-MCF/D	with that from any other lease or pool, with that from any other lease or pool, I OII Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, ANI CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure QII-Bbls. Length of Test Tubing Pressure	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET DEPTH SET depth or be for full 24 hours) Producing Method (l'low, pump, gas li, Casing Pressure Water-Bbis. Bbls. Condensate/MMCF Casing Pressure OIL CONSERVA	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT SACKS CEMENT and must be equal to or exceed top allow- (t, etc.) Choke Size Gas-MCF Gravity of Condensate Choke Size
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations HOLE SIZE Image: GAS WELL Actual Prod. During Test Image: GAS WELL Actual Prod. Test-MCF/D Testing Method (pitot, back pr.) I. CERTIFICATE OF COMPLIA	with that from any other lease or pool, ition - (X) OII Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, ANI CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure QII-Bbls. Length of Test Tubing Pressuro NCE	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow- (t, etc.) Choke Size Gas-MCF Gravity of Condensate Choke Size
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool HOLE SIZE HOLE SIZE Image Pool Perforations HOLE SIZE Image Pool Image Perforations Image	with that from any other lease or pool, ition - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure OII-Bbls. Length of Test Tubing Pressure NCE d regulations of the Oil Conservation I with and that the information given	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET DEPTH SET depth or be for full 24 hours) Producing Method (l'low, pump, gas li, Casing Pressure Water-Bbis. Bbls. Condensate/MMCF Casing Pressure OIL CONSERVA	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT SACKS CEMENT and must be equal to or exceed top allow- (t, etc.) Choke Size Gas-MCF Gravity of Condensate Choke Size
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool Perforations HOLE SIZE Image: Hole Size HOLE SIZE Image: Hole Size	with that from any other lease or pool, ition - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure OII-Bbls. Length of Test Tubing Pressure NCE d regulations of the Oil Conservation	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT SACKS CEMENT and must be equal to or exceed top allow- (t, etc.) Choke Size Gas-MCF Gravity of Condensate Choke Size NTION COMMISSION , 19
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool HOLE SIZE HOLE SIZE Image Pool Perforations HOLE SIZE Image Pool Image Perforations Image	with that from any other lease or pool, ition - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure OII-Bbls. Length of Test Tubing Pressure NCE d regulations of the Oil Conservation I with and that the information given	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allow- (t, etc.) Choke Size Gas-MCF Gravity of Condensate Choke Size
give location of tanks. If this production is commingled V. COMPLETION DATA Designate Type of Comple Date Spudded No Change Pool HOLE SIZE HOLE SIZE Image Pool Perforations HOLE SIZE Image Pool Image Perforations Image	with that from any other lease or pool, ition - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test Tubing Pressure OII-Bbls. Length of Test Tubing Pressure NCE d regulations of the Oil Conservation I with and that the information given	give commingling order number: New Well Workover Deepen Total Depth Top Oll/Gas Pay D CEMENTING RECORD DEPTH SET fter recovery of total volume of load oil epth or be for full 24 hours) Producing Method (l'low, pump, gas li Casing Pressure Water - Bbls. Bbls. Condensate/MMCF Casing Pressure OIL CONSERVA APPROVEN BY SUPERVISO	Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT SACKS CEMENT and must be equal to or exceed top allow- (t, etc.) Choke Size Gas-MCF Gravity of Condensate Choke Size NTION COMMISSION , 19

3/7/19

This form is to be filed in compliance with RULE 1104. If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

(Signature) (Signature) District Prod. & Drlg. Supt.