District H 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Oh. CONSURVATION DEVISION 1220 South St. Francis Dr. Santa Fe, NM 87505			5. Indicate Type of Lease STATE X FEE 6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM				011658	
87505 SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMET" (FORM C-101) FOR SUCH PROPOSALS: PROPOSALS: PROPOSALS:				Aztec State	
Oil Well X Gas Well [] Other				8. Well No.1	
Cactus Operating Co, LLC				D. D. L. William	
3. Address of Operator				9. Pool name or Wildcat Vacuum Grayburg San Andres	
P.O. Box 98, Lovington, NM 88260				Vacuum Grayourg San Andres	
4. Well Location					
Unit Letter N : 1984 feet from the West line and _660 feet from the South line					
Section 15	Township	17S Rai	nge 34E	NMPM	County Lea
	Elevation (Show when L				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF					
PERFORM REMEDIAL WORK	PLUG AND ABANDO	N 🗌	REMEDIAL WOR	RK	X. ALTERING CASING —
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DE		ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST A CEMENT JOB	AND	200H 27
OTHER:			OTHER:		n31
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. December 2000 - MIRUSU. Pull tubulars after tubing parted at 4500'. Fish rods in casing from 2950' to 3661'. Work additional 7 days					
recovering fish to 3692'. Secure permission to set CIBP at 3600' and recomplete to Seven Rivers and Yates formation. RIH w/wireline. set CIBP @ 3600'. Dump bail 35' cement on top of CIBP. RIH w/3 1/16ths gun. Perforate 4 SPF at 3258' - 65', 3244' - 46', 3238' - Set CIBP @ 3600'. Dump bail 35' cement on top of CIBP. RIH w/3 1/16ths gun. Perforate 4 SPF at 3258' - 65', 3244' - 46', 3238' - Set CIBP @ 3600'. Dump bail 35' cement on top of CIBP. RIH w/3 1/16ths gun. Perforate 4 SPF at 3258' - 65', 3244' - 46', 3238' - Set CIBP @ 3600'.					
and and are angles for T-1-1-for being Dill w/ngcler hinng Sei Dacker al 2047 allu Evaluate, syndous is minimum more					
40', 3003' - 05', 2954' - 56'. Total of 64 flotes. Kirl wipacker, tubilg. Set pasted at 20'. Acidize well w/1000 gallons 15% NEFe HCl. Swab back 18 BLW. Lack 16 BHLR. No oil or gas show. Swab additional two days.					
Minimal fluid. No oil or gas show. POOH laying down tubing, packer. SI well pending evaluation.					
THE PERSON OF TH					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE / Little DATE February 5, 2003_					
Type or print name William V. Palmer Telephone No. 505.396.7560					
(This space for State use)					
APPPROVED BY	ORI	GITITLE. ~	1		DREB_1 1 2003
Conditions of approval if any					
CONDITIONS OF APPROVAL, IT MAY SEER					
ATTACH MANAGER					

L