STATE OF NEW MEXICO NEHGY AND MINERALS DEPARTMENT

** ** ****** ***	l		
PILINIPUTI			
ANTAFE			
16.6			
1.0.4,			
AND DEFICE			
MANIFORTER	טיג		
	0 / 6		
PERATOM			
LOBATION OFF			

OIL CONSERVATION DIVISION P. O. BOX 2008 SANTA FE, NEW MEXICO 87501

Form C-104 Revised 10 01-78 Format 06-01-83 Page 1

Separate Forms C-104 must be filed for each pool in multiply

REQUEST FOR ALLOWABLE DHA AUTHORIZATION TO TRANSPORT OIL AND NATURAL GAS

) peratur						
Hondo Oil and Gas Company						
ddress						
P. O. Box 2208, Roswell, New	Mexico 88201		Other (Flease	explain		
 -	·		•	rive march 1, 19	87	
<u> </u>	ighend Gae 🔲 Co	onden sale				
change of ownership give name od address of previous owner						
. DESCRIPTION OF WELL AND LEASE						
ease Name Well No.	Poul Name, Including I	Cornation		Kind of Leuse	n - a 14	Ledes No.
Mescalero Ridge Unit 35 14	Pearl Queen			State, Federal or Fee	Fed N	M 7465B
Unii Leller D : 660 Feel Fro	m The North Lin	e and	990	_ Feet From The	West	
Une of Section 35 Township 19	Range 3	4E	, имрм,	Lea		County
Shell Pipeline Shell Pipeline Phillips 66 Natural Gas Comp (well produces off or liquids, for location of tonks. F 35 this production is commingled with that from an OTE: Complete Parts IV and V on reverse s.	or Dry Gos Dry Gos Dry Gos Dry Rye. 19 34 y other lease or pool,	P. O Address (4001	Box 264 Give address if Penbrook tually connecte Yes	<u> </u>	77001	
and the second s		OIL CONSERVATION DIVISION				
I. CERTIFICATE OF COMPLIANCE		I I.		18 F 1		
hereby certify that the fules and regulations of the Oil Conservation Division have early with and that the information given is true and complete to the best of y knowledge and belief.		APPROVED JUL 2 3 1987 . 19 BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT I SUPERVISOR				
Adjust Collis (Signalwe) Production Clerk (Illie) July 14, 1987		This form is to be filed in compliance with AULE 1104. If this is a request for allowable for a newly drilled or decrenes well, this form must be accompented by a tabulation of the dayjetion taken on the well in accordance with AULE 111. All sections of this form must be filled out completely for allow able on new and recompleted wells. Fill out only Sections I. II. III, and VI for changes of Swarr well marge or number, or transporter, or other such change of condition				
· 1		able on new and recompleted wells. Fill out only Sections I. II. III. and VI for changes of Swarr, well mains or number, or transporter, or other such change of condition				

completed wells.