

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ File ☐
5. State Oil & Gas Lease No.
B-155

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A WELL TO A DIFFERENT RESERVOIR.
USE MAPA 10-1-79 FOR PERMIT AND FORM C-103 FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER _____
2. Name of Operator
TEXACO Inc.
3. Address of Operator
P.O. Box 728, Hobbs, NM 88240
4. Location of Well
UNIT LETTER **J** **2090** FEET FROM THE **South** LINE AND **2086** FEET FROM
THE **East** LINE, SECTION **36** TOWNSHIP **17-S** RANGE **34-E** RANGE.

7. Unit Agreement Name
-
8. Name of Lease Name
N.M. "O" St. NCT-1
9. Well No.
25
10. Field and Pool, or Wildcat
Vacuum Glorieta
12. County
Lea

11. Elevation (Show whether DF, RT, GR, etc.)

3990' (GR)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☒ Repair water flow	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Pull rods & pump. Install BOP. Pull tubing.
2. Set RBP @ approx. 5000'. Log well.
3. Squeeze 11-3/4" - 8-5/8" annulus w/600 sx Class "C" Cement. WOC & test.
4. Install production equipment. Test & place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *John Rayan* TITLE Asst. Dist. Supt. DATE 7-25-80
Orig. Signed by
John Rayan
APPROVED BY Geologist TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: