

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name North Vacuum Abo Unit
9. Well No. 112
10. Field and Pool, or Wildcat Vacuum Abo North
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - 1 (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER
2. Name of Operator Mobil Producing TX. & N.M. Inc.
3. Address of Operator Nine Greenway Plaza, Suite 2700, Houston, Texas 77046
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>860</u> FEET FROM THE <u>West</u> LINE, SECTION <u>25</u> TOWNSHIP <u>17S</u> RANGE <u>34E</u> N.M.P.M.
13. Elevation (Show whether DF, RT, CR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Workover, recomplate	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-15-82
10,228 TD, 9998 PBTD, Glorietta 6009-6038, Abo 8411-8447. WIH w/6-1/8" OD X 4-7/8" ID X 4' Cur Rite shoe, 1 - 5 1/2" x 29' WP, 5 - 4 1/4" Col's, strap in hole, tag up @ 6060, work mill over fish 6060-6064 & stopped, milled over fish 6064-6066 w/no circ, pull shoe up.

1-18-82
Milled 6", mill quit, POH w/shoe (cut-rite worn out), RIH w/4-11/16" X 10' OS w/2-3/8" grapple, 4 1/4" Bowen accelerator sub, 3 - 4 1/4" DC's tagged fish @ 6060. Caught fish, jarred on fish 2 times, came off fish, unable to recatch fish, POH w/12 jts 2-3/8" buttress.

1-19-82
POH w/OS, RIH w/4-11/16" OS w/2 1/4" gal, BS, Johnston jars, 2 - 4 1/4" DC + Bowan accelerator sub + 3 4 1/4" DC on 2-3/8 tbg, tagged fish @ 6060, caught fish jarred on fish 2 1/2 hrs, pkr came loose, POH w/2-3/8 tbg, fishing tools, rec 10' piece of cork screwed tbg, SN 7" Guiberson pkr, perfs & MA, LD DC's & fishing tools.

1-20-82
RIH w/2-3/8 tbg to 8353, tbg perfs 8319 to 8323, Guiberson Uni Pac VI @ 8313 to 8319, set w/10,000# tension, SN @ 8312, 70 jts 2-3/8" 8rd tbg, Guiberson parallel anchor @ 6125, 196 jts 2-3/8" 8rd tbg, HT tbg to 5000 psi, landed long string, RIH w/1-3/4" x 6' parallel anchor stringer, perfs, SN & cross over on GST, Hydril tbg to 6100.

(Cont'd)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lammy A. Meyer TITLE Authorized Agent DATE 2-3-82
APPROVED BY Lee O. Meyer TITLE Lee O. Meyer DATE 2-3-82
CONDITIONS OF APPROVAL, IF ANY

17. (Cont'd)

1-21-82

Fin RIH w/PA stringer & 2-3/8 tbg to PA @ 6125, 10,000# T, perf 6111-6119, SN @ 6102, RIH (Abo) 1" x 8' GA 2 x 1½ x 24 pump, 99 - 7/8 rods, 228 - 3/4 rods, RIH (Glor) 1" x 8' GA, 2 x 1½ x 16 pump, 170 - 3/4 rods, 70 - 7/8 rods, spaced out rods, hung well on, loaded Abo w/8 BLW test 500 psi/OK, loaded Glor w/10 BLW, test 500 psi/held OK, RD & rel X-pert WS @ 5:30 PM 1-21-82, rel to prod.

1-24-82

Abo Zone: POP 1-22-82, P 75 BNO + 224 BNO + 178 BLW/98 hrs.

1-25 thru 28-82

Testing well.