

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT..." (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Mobil Oil Corporation		5. State Oil & Gas Lease No. B-1520
3. Address of Operator Box 633, Midland, Texas 79701		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>L</u> <u>1880</u> FEET FROM THE <u>South</u> LINE AND <u>510</u> FEET FROM THE <u>West</u> LINE, SECTION <u>24</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> N.M.P.M.		8. Farm or Lease Name Bridges State
		9. Well No. 116
		10. Field and Pool, or Wildcat Vacuum Wolfcamp
15. Elevation (Show whether EF, RT, GR, etc.) 4030 GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Abandon Wolfcamp Zone</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Abandon Wolfcamp Zone and complete as a single in the vacuum Abo
Set cast iron bridge plug at approx. 9520' and spot 10 sx cement plug on top
(35' plug)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine C. Tucker

TITLE Authorized Agent

DATE 7-14-74

Also Signed by
John Runyan
Geologist

Geologist

Jul 17 1975