· · · · · · · · · · · · · · · · · · ·		
NO. OF COPIES RECEIVED		Form C-103 Supersedes Old
DISTRIBUTION	unant agging 8. C. C.	C-102 and C-103
ANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
TILE		
U.S.G.S.	Jan 23 9 55 AM '67	5a. Indicate Type of Lease
LAND OFFICE		State 🗷 Fee.
OPERATOR		5. State Oil & Gas Lease No.
		B-3196
(DO NOT USE THIS FORM	SUNDRY NOTICES AND REPORTS ON WELLS A FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
		7. Unit Agreement Name
OIL GAS WELL WELL	other. Dry Completion	
2. Name of Operator		8. Farm or Lease Name
	•	State H-35
Continental Oil	Company	
Continental Oil Address of Operator	Company	9. Well No.
Address of Operator		
P. O. Box 460, H		9. Well No.
P. O. Box 460, H.	obbs, New Mexico	9. Well No. 13 10. Field and Pool, or Wildcat
P. O. Box 460, H		9. Well No. 13 10. Field and Pool, or Wildcat
P. Q. Box 460, H. 4. Location of Well UNIT LETTER	obbs, New Mexico	9. Well No. 13 10. Field and Pool, or Wildcat Vacuum Glorieta
P. Q. Box 460, H. 4. Location of Well UNIT LETTER	Obbs, New Mexico 990 FEET FROM THE North LINE AND 1650 FEET FROM 16, SECTION 35 TOWNSHIP 178 RANGE 348 NMPM.	9. Well No. 13 10. Field and Pool, or Wildcat Vacuum Glorieta
P. Q. Box 460, H. 4. Location of Well UNIT LETTER	Obbs, New Mexico 990 FEET FROM THE North LINE AND 1650 FEET FROM 16, SECTION 35 TOWNSHIP 178 RANGE 348 NMPM. 15. Elevation (Show whether DF, RT, GR, etc.)	9. Well No. 13 10. Field and Pool, or Wildcat Vacuum Glorieta
P. Q. Box 460, H. 4. Location of Well UNIT LETTER THE ROST LIN	990 FEET FROM THE NORTH LINE AND 1650 FEET FROM 16, SECTION 35 TOWNSHIP 178 RANGE 348 NMPM. 15, Elevation (Show whether DF, RT, GR, etc.) 4018 DF	9. Well No. 13 10. Field and Pool, or Wildcat Vacuum Glorieta 12. County Lea
P. Q. Box 460, H. 4. Location of Well UNIT LETTER THE Rest LIN	990 FEET FROM THE North LINE AND 1650 FEET FROM 16, SECTION 35 TOWNSHIP 178 RANGE 34E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4018 DF Check Appropriate Box To Indicate Nature of Notice, Report or Otl	9. Well No. 13 10. Field and Pool, or Wildcat Vacuum Glorieta 12. County Lea
P. Q. Box 460, H. 4. Location of Well UNIT LETTER THE Rest LIN	990 FEET FROM THE NORTH LINE AND 1650 FEET FROM 16, SECTION 35 TOWNSHIP 178 RANGE 34E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4018 DF Check Appropriate Box To Indicate Nature of Notice, Report or Other	9. Well No. 13 10. Field and Pool, or Wildcat Vacuum Glorieta 12. County Lea ner Data
Address of Operator P. Q. Box 460, H. LOCATION OF WELL UNIT LETTER THE BOST LIN NOTICE	990 FEET FROM THE NORTH LINE AND 1650 FEET FROM 16, SECTION 35 TOWNSHIP 178 RANGE 348 NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4018 DF Check Appropriate Box To Indicate Nature of Notice, Report or Otle Of INTENTION TO:	9. Well No. 13 10. Field and Pool, or Wildcat Vacuum Gloriata 12. County Lea ner Data REPORT OF:
Address of Operator P. O. Box 460, H. LOCATION OF WELL UNIT LETTER THE ROST LIN 16. NOTICE PERFORM REMEDIAL WORK	990 FEET FROM THE NORTH LINE AND 1650 FEET FROM 15. Elevation (Show whether DF, RT, GR, etc.) 4018 DF Check Appropriate Box To Indicate Nature of Notice, Report or Otle OF INTENTION TO: PLUG AND ABANDON REMEDIAL WORK	9. Well No. 13 10. Field and Pool, or Wildcat Vacuum Gloriata 12. County Lea TREPORT OF: ALTERING CASING
Address of Operator P. O. Box 460, H. Location of Well UNIT LETTER THE REST LIN 16. NOTICE PERFORM REMEDIAL WORK TEMPORARILY ABANDON	990 FEET FROM THE NORTH LINE AND 1650 FEET FROM 15. Elevation (Show whether DF, RT, GR, etc.) 4018 DF Check Appropriate Box To Indicate Nature of Notice, Report or Otle OF INTENTION TO: PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	9. Well No. 13 10. Field and Pool, or Wildcat Vacuum Gloriata 12. County Lea TREPORT OF: ALTERING CASING
Address of Operator P. O. Box 460, H. Location of Well UNIT LETTER THE REST LIN 16. NOTICE PERFORM REMEDIAL WORK TEMPORARILY ABANDON	990 FEET FROM THE NORTH LINE AND 1650 FEET FROM 15. Elevation (Show whether DF, RT, GR, etc.) 4018 DF Check Appropriate Box To Indicate Nature of Notice, Report or Otle OF INTENTION TO: PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS CASING TEST AND CEMENT JOB	9. Well No. 13 10. Field and Pool, or Wildcat Vacuum Glorieta 12. County Lea TREPORT OF: ALTERING CASING

This well was drilled to 6033' TD. No production was encountered. The well was plugged and abandoned using the fellowing procedure:

Set cement plugs as follows w/10# mud between plugs:

5885-6033' w/50 sx Incor 4360-4800' w/150 sx Incor 2820-2970' w/50 sx Incor 2530-2680' w/50 sx Incor 1475-1625' w/50 sx Incor 0-30' w/10 EX Incor

This work was performed on 11-8-66.

It was found that the well was not successfully plugged. Found cement stringers at 1349'. Drilled cement from 1349-1544' and 2530-2680'. Circulated hole and conditioned mud. Set 50 sx Class "B" cement plug w/4# salt and 15# sand per sx w/3% calcium chloride from 1447-1625'. Shut in 24 hrs., SITP-175#. Drilled out contaminated cement plugs from (Continued)

NO. OF COPIES RECEIVED	1	Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSURVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE	00 0 m N 257	2.11001210 1 1-000
U.S.G.S.	JAN 23 9 55 AM '67	5a. Indicate Type of Lease
LAND OFFICE		State Fee
OPERATOR		5. State Oil & Gas Lease No.
SUNDR (DO NOT USE THIS FORM FOR PRO USE "APPLICAT	RY NOTICES AND REPORTS ON WELLS OPPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL WELL	OTHER-	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
3. Address of Operator		9. Well No.
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER,	FEET FROM THE LINE AND FEET	T FROM
THELINE, SECTIO	ON TOWNSHIP RANGE	NMPM. ((((())))
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		12. County
Check A	Appropriate Box To Indicate Nature of Notice, Report of	or Other Data
NOTICE OF IN	ITENTION TO	UENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		<u> </u>
17. Describe Proposed or Completed Ope	erations (Clearly state all pertinent details, and give pertinent dates, inc	luding estimated data of starting
work) SEE RULE 1103.	in a group portune access, and	tuting estimated date of starting any proposed
(Continued)		
hole and tested w/1,00 Hole between plugs was status of plugging ope 11-19-66.	tainer at 1480'. Failed to pump under retainer at 1480'. Failed to pump under retained. Set 90 sx Class "C" coment plug on retains filled w/10f mud. Shut in. Top plug not erations. This sequence of work started on	iner at 2,000#. Circulated tainer from 1112-1480'. set in order to observe
Metr Mes opserve	ed and found to be satisfactorily plugged.	
	at 1070' w/5 sx coment on top. Set coment s original condition and erected well marker 12-31-66.	
	above is true and complete to the best of my knowledge and belief.	
SIGNED. 6 C. I.C.	MESON TITLE Assistant District Manag	er January 20, 1967
PPROVED BY John IV.	Runyan TITLE	
ONDITION OF APPROVAL, IF ANY:	11146	DATE