

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A	7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company	8. Farm or Lease Name C. M. Selby
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201	9. Well No. 2
4. Location of Well UNIT LETTER A 990 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 18 TOWNSHIP 17-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Midway-Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3790' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

This well has been plugged and abandoned in the following manner:

Set CIBP in 4½" casing @ 8803' and capped w/20 sk Class "A" cement plug 8515-8803'. Shot 4½" casing @ 5558', pulled 180 jts 4½" casing. Spotted 30 sk Class "A" cement plug 5435-5558', 30 sk Class "A" cement plug half in & half out of 8-5/8" casing Shoe @ 4791'. Shot 8-5/8" casing @ 1521', pulled 47 jts 8-5/8" casing. Spotted 30 sk cement plug half in & half out of 8-5/8" stub @ 1520'. Spotted 30 sk cement plug half in & half out of 13-3/8" casing shoe @ 350'. Set 10 sk Class "A" cement plug in top of well. 9½/gal salt gel mud was used to spot all plugs. Erected dry hole marker. Well plugged & abandoned 9/3/70.

Your office will be notified when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>P.D. Sletcher</u>	TITLE <u>Dist. Drlg. Supervisor</u>	DATE <u>9/9/70</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>MAR 26 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

SEP 11 1970

OIL CONSERVATION COMM.
HOUSE, R. 17