

OF COPIES RECEIVED	
DISTRIBUTION	
STATE	
E	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG-2001	

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <b>Dry Hole</b>	7. Unit Agreement Name ---
Name of Operator <b>Read &amp; Stevens, Inc.</b>	8. Firm or Lease Name <b>Quail State</b>
Address of Operator <b>P. O. Box 1518, Roswell, NM 88201</b>	9. Well No. <b>3</b>
Location of Well UNIT LETTER <b>I</b> <b>1830</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM <b>East</b> LINE, SECTION <b>11</b> TOWNSHIP <b>19-S</b> RANGE <b>34-E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Quail Queen</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3960' GR</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
---	--	--	--

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.)

Old TD 10,500', cleaned out to 1098'. Plugged and abandoned as follows:

1. Laid down drill collars and ran tubing open ended to 1020'.
2. Set 75 sx. Class H cement plug 1020' to 920'.
3. Set 90 sx. Class H cement plug 400' to 300'.
4. Set 10 sx. Class H cement plug 10' to surface.
5. Installed Dry Hole marker.
6. Released rig @ 3:00 P.M., 1-31-79.

17. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>John L. Anderson Jr.</u>	TITLE <u>Agent</u>	DATE <u>2-12-79</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL &amp; GAS</u>	DATE <u>2-12-79</u>
CONDITIONS OF APPROVAL, IF ANY:		